



Home

Create New

Estimate

Edit

Preview



Vehicle
Information

Plate Number
SLC7737D

Edit

Case Number
MPC2022D0008381

Edit

Brand
BMW

Model Details
3-Series

Body Type
Sedan

Insurance company
-

Edit

 Attachment

Technician
-

Edit

SA
LKK_assignments

Edit

Parts Manager
-

Edit

No data

Remarks 1 remarks

Submit

2023-01-10 22:19 Assessor Supervisor-Insurlogic 1 6584981566

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic

Amount : \$5296.80

Check items: \$2807.25

Lump sum: \$4200.00 (Before Check Items)

Repair Duration: 4 - 5 days

Parts
Total
\$0.00

Labor
Total
\$0.00

Repair Cost
(Part +
Labor)
\$0.00

Discount

%   0 %

Excess

\$

Tax

%

Repair
Total
\$0.00

Estimate

Save