

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sundari Nagarajan

Date: 10 Jan 2023

Preliminary Advice

Vehicle No	: SLC7737D	Accident Date	: 04/11/2022
Make	: BMW 318I	Policy No.	: D21MPC0002642_01
Assignment Date	: 15/11/2022	Excess	: S\$0.00
Date of Inspection	: 16/11/2022	Est. Duration of Repair	: 6
Inspection At	: GALAXY AUTO CARE PTE LTD (HQ) 13 KAKI BUKIT ROAD 4, #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,619.35
Revised Amount	:S\$	5,296.80
Check Items (Estimated)	:S\$	2,840.50
Total	:S\$	8,137.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	34,549.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,451.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.