



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNF3043J

Mr Lee

166 Tampines Street 12
#06-343
Singapore 521166

Mobile: +6592224472

Vehicle & Document Information

WIP No 60968
Reg No/Reg Date SNF3043J / 02/01/2020
Date In/Mileage / 0
Chassis No WDD1183872N072417X
Engine No 28291480274664
Make/Model MB/CLA 200 COUPE
Colour/Trim 029 914 Sun Yellow / 046 651 ARTICO DINA

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSM00128	Cash	15/11/2022/ 14:27	VS	356 / Vincent Seah					
7 REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE :SP2002059853 // 15.11.2022									
DRIVE IN/EXCESS :15.11.2022 //									
DATE IN/DATE SURVEY:15.11.2022 //									
BY/AUTHORIZED ON :									
M BPNSUN									
SUNDRIES									
A BPILAB									
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT									
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT									
S BPNSUB									
SUPPLY 1 SET NUMBER PLATE WITH HOUSING. NETT									
REAR									
A BPILAB									
REMOVE AND TRANSFER REAR BOOT COMPONENT TO NEW PANEL									
A BPILAB									
REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT									
A BPILAB									
PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.									
A BPIRES									
RESPRAY ON REAR BUMPER, BOOT, END PANEL AND ACCIDENT AFFECTED AREA									
M	REAR BUMPER	de				1.00	1612.14	00.00	1612.14
M	ELECTRICAL WIRING HARNESS ?					1.00	160.75	00.00	160.75
M	RIGHT BRACKET, BUMPER ?					1.00	77.25	00.00	77.25
M	LEFT BRACKET, BUMPER ?					1.00	77.25	00.00	77.25
M	RIGHT TAILPIPE TRIM at					1.00	121.89	00.00	121.89
M	LEFT REFLECTING EMITTER ?					1.00	40.87	00.00	40.87

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNF3043J

Mr Lee

166 Tampines Street 12
#06-343
Singapore 521166

Mobile: +6592224472

Vehicle & Document Information

WIP No **60968**
Reg No/Reg Date **SNF3043J / 02/01/2020**
Date In/Mileage **0**
Chassis No **WDD1183872N072417X**
Engine No **28291480274664**
Make/Model **MB/CLA 200 COUPE**
Colour/Trim **029 914 Sun Yellow / 046 651 ARTICO DINA**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	15/11/2022/ 14:27	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RIGHT REFLECTING EMITTER	1.00	40.87	00.00	40.87
M LEFT COVER GRILL-TAILPIPE X	1.00	41.87	00.00	41.87
M RIGHT COVER GRILL-TAILPIPE X	1.00	41.87	00.00	41.87
M RHR CHROME TRIM STRIP	1.00	152.42	00.00	152.42
M DISTANCE SENSOR	6.00	195.43	00.00	1172.58
M SPACER RING	6.00	7.10	00.00	42.60
M LHR BASIC CARRIER FOR BUMPER	1.00	103.89	00.00	103.89
M RHR BASIC CARRIER FOR BUMPER	1.00	86.67	00.00	86.67
M CTR BRACKET, REAR BUMPER	1.00	66.53	00.00	66.53
M CTR BASIC CARRIER FOR BUMPER	1.00	100.68	00.00	100.68
M EXPANSION RIVET	2.00	1.19	00.00	2.38
M EXPANSION RIVET	2.00	1.19	00.00	2.38
M REAR BUMPER CHROME TRIM STRIP	1.00	162.54	00.00	162.54
M TRUNK LID	1.00	1886.88	00.00	1886.88
M SPRING DAMPER	2.00	14.23	00.00	28.46
M BOOT WEATHERSTRIP	1.00	194.33	00.00	194.33
M SPRING DAMPER	2.00	12.72	00.00	25.44
M LHR HINGE BRACKET	1.00	289.39	00.00	289.39
M RHR HINGE BRACKET	1.00	289.39	00.00	289.39
M BOOT HANDLE STRIP	1.00	149.88	00.00	149.88
M CLA 200 MODEL PLATE	1.00	112.49	00.00	112.49
M RELEASE HANDLE	1.00	187.60	00.00	187.60
M MERCEDES STAR	1.00	164.74	00.00	164.74
M LOCK	1.00	333.55	00.00	333.55
M STRIKER	1.00	23.69	00.00	23.69
M REAR-END PANEL	1.00	1146.08	00.00	1146.08
M CROSSMEMBER, REAR	1.00	478.34	00.00	478.34
M LOAD COMPARTMENT WELL	1.00	774.67	00.00	774.67
M REAR UNDER COVER, SUBSTRUCTURE	1.00	166.09	00.00	166.09
M LH REAR LAMP COMBINATION	1.00	713.21	00.00	713.21
M RH/ REAR LAMP COMBINATION	1.00	713.21	00.00	713.21
M BOOT LEFT REAR LAMP COMBINATION	1.00	555.46	00.00	555.46
M BOOT RIGHT REAR LAMP COMBINATION	1.00	555.46	00.00	555.46

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett **22,910.79**
7% GST on **22910.79** **1603.76**

Total Payable **24,514.55**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop