LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 17 Nov 2022

Preliminary Advice

Vehicle No: SNF3043JAccident Date: 15/11/2022Make: MERCEDES-BENZ C200Policy No.: SP2002059853

Assignment Date : 15/11/2022 Excess : S\$0.00

Date of Inspection : 16/11/2022 Est. Duration of Repair : 10 DAYS

Inspection At : CYCLE & CARRIAGE INDUSTRIES PLE LIMITED

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 22,910.79 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 16,057.74 |
| Check Items (Estimated) | :S\$ | 4,096.61 |
| Total | :S\$ | 20,154.35 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 178,000.00

 COE / PARF Rebate
 :S\$ 59,167.00

Salvage Value :S\$

Margin for Repair :S\$ 118,833..00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have | ve also confirmed excess and policy coverage. |
|-------|---|---|
| | Kindly let us have your authorisation. | |

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.