



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HOLMAN FENWICK WILLAN SINGAPORE LLP 30 RAFFLES PLACE, #24-01, OXLEY @ RAFFLES, SINGAPORE 048622			Ref: CS/LAW22011466/Uwy3e2 Date: 03/01/2023 Code: L181	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	WC 7959A	Veh. Inspected	YP 3793U	
Policy No.		Coverage (\$)	0.00	
Claim No.	HFWS.P.FID2086931	Excess (\$)	0.00	
Assign From	DARRYL ANDREW QUEK	Assign Date	15/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi fuso FK62 (M)	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FK62FMA30147	Colour	WHITE	
Odometer	70992 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/70 R19.5	FALKEN	6 mm	
L/H Front Tyre	245/70 R19.5	FALKEN	6 mm	
R/H Rear Tyre	245/70 R19.5 (D)	FALKEN	6/6 mm	
L/H Rear Tyre	245/70 R19.5 (D)	FALKEN	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/11/2022	Inspection Date	16/11/2022	
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	