

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

have 7 days 3.11
mile 1515-81 Dashboard \$2984.74
ABS light and Edge check light on
2/1/23 1/5 \$11200 in/normal will/can @ 09 days (Red \$ 26,110.62 / 70%)



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Date of Accident : 08 November 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Loaded Services Pte Ltd

Date : 10 November 2022

9 days

not Authorized
der
meray
16/11/22
L/S# 11,200/
who? who? who? who?

124

Estimate To Repair YP3793U - Mitsubishi FUSO FK62FMZ1RDEB

Chassis No : FK62FMA30147

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
01	1 pc	front bumper <i>Best</i>	\$ 1,600.00
02	2 ps	front bumper bracket @ \$327.13 <i>17</i>	\$ 654.26
03	2 ps	headlamp @ \$1610.00 <i>17</i>	\$ 3,220.00
04	2 ps	headlamp trim @ \$165.00 <i>11</i>	\$ 330.00
05	2 ps	headlamp bracket @ \$165.00 <i>11</i>	\$ 330.00
06	2 ps	front bumper fog lamp @ \$220.06 <i>17</i>	\$ 440.12
07	2 ps	front bumper fog lamp bracket @ \$130.00 <i>17</i>	\$ 260.00
08	1 pc	front grille <i>Che</i>	\$ 1,500.00
09	10 ps	front grille clips @ \$5.00 <i>17</i>	\$ 50.00
10	1 pc	bonnet <i>D></i>	\$ 3,500.00
11	2 ps	front corner panel @ \$912.26 <i>17</i>	\$ 1,824.52
12	2 ps	front corner panel signal lamp @ \$120.00 <i>17</i>	\$ 240.00
13	1 pc	front bumper reinforcement <i>Best</i>	\$ 720.00
14	1 pc	front panel <i>Body</i>	\$ 1,600.00
15	1 pc	front windscreen glass <i>Che</i>	\$ 2,657.90
16	1 pc	front windscreen moulding <i>7m</i>	\$ 95.00
17	1 pc	audio antenna <i>Daye / n/c</i>	\$ 180.00
18	1 pc	aircon condenser pressure pipe <i>17</i>	\$ 150.00
19	1 pc	aircon condenser high pressure pipe <i>17</i>	\$ 150.00
20	1 pc	radiator spare tank <i>de</i>	\$ 450.00
21	1 pc	front grille emblem badge <i>clw grille</i>	\$ 160.00
22	1 pc	front grille Fighter badge <i>clw grille</i>	\$ 120.00
23	1 pc	wiper motor <i>11</i>	\$ 580.00
24	2 ps	wiper linkage @ \$220.00 <i>Best</i>	\$ 440.00
25	2 ps	wiper arm @ \$80.00 <i>Best</i>	\$ 160.00
26	1 pc	wiper blade <i>Best</i>	\$ 60.00
27	1 pc	dashboard <i>Cut / 70.00</i>	\$ 2,600.00
28	1 pc	dashboard reinforcement <i>17</i>	\$ 1,100.00
29	1 pc	dashboard center top cover <i>17</i>	\$ 450.00
30	1 pc	dashboard center cover <i>11</i>	\$ 620.00
31	1 pc	dashboard console left <i>17</i>	\$ 550.00
32	1 pc	dashboard lower cover <i>11</i>	\$ 280.00
33	1 pc	steering cloumn top cover <i>17</i>	\$ 220.00
34	1 pc	steering cloumn bottom cover <i>17</i>	\$ 220.00
35	1 pc	aircon blower unit <i>Che</i>	\$ 1,800.00

1485.82

3011.69

1600

245

2200.00



陳林摩嚙私人有限公司
TAN LIM MOTOR PTE LTD

Date of Accident : 08 November 2022

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Loaded Services Pte Ltd

Date : 10 November 2022

Estimate To Repair YP3793U - Mitsubishi FUSO FK62FMZ1RDEB
Chassis No : FK62FMA30147

S/No	Quantity	Description	Amount
<u>NETT ITEMS</u>			
36	1 pc	cooling coil ^ ^	\$ 2,600.00
37	2 ps	front panel outer handle @ \$160.00 o/s Dye	\$ 320.00
38	2 ps	front panel outer handle bracket @ \$240.00 n	\$ 480.00
39	2 ps	front panel outer handle cover @ \$40.00 o/s MYS	\$ 80.00
40	1 pc	front bonnet emblem n	\$ 140.00
41	1 pc	bonnet lock TM	\$ 180.00
Less 10% 25%			\$ 33,111.80
			\$ 3,311.18
			\$ 29,800.62
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit front windscreen glass.	\$ 300.00
02		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 450.00
03		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 180.00
04		To check electrical lighting concerned.	\$ 250.00
05		To resupply I.U. bracket.	\$ n 30.00
06		Towing charges.	\$ 450.00
07		To rust-proofing of the affected areas.	\$ 300.00
08		To remove and replace front wiper motor and linkage.	\$ n 250.00
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,500.00
10		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 7,510.00
Total			\$ 37,310.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7- 15437.51
252
11578.13
2540
14118.13
252
11294.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	432N
Vehicle Details	
Vehicle No.:	YP3793U
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2022
Vehicle Make:	MIITSUBISHI
Vehicle Model:	FUSO FK62FMZ1RDEB
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	6M60215771
Chassis No.:	FK62FMA30147
Maximum Power Output:	-
Open Market Value:	\$53,871.00
Original Registration Date:	29 Aug 2016
First Registration Date:	29 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$2,694.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$25,872.00
COE Rebate Amount:	\$9,785.00
Total Rebate Amount:	\$9,785.00

The information contained herein is correct as at 16 Nov 2022

OK

POS
F10 NOV

GAO

Express Towing Services

-----Yee-Call, We Tow - Fast . Secured . Reliable

Alan Pemimpin Halcyon 2 #C01-02 Singapore 577200 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: <http://www.gaoexpress towing.sg>

098
1055
1220

Pay 11/2002

will

CASH SALE/WORK ORDER

寶號

Messrs: Cash workshop

車號

Vehicle No: YP37930

車型

Model No: 24FT BOX

時間(日/夜)

Time (day/night): 07220001

Contact No: 07220001

由

Location: 61 Alps Ave

到

To: 1, Defu Lane

其他

Others: 180

Cash \$: 180

經手人

Authorised By: Jim

Tow Truck

Driver Name: Eaka Synov

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。

The company accepts no responsibility for damages or

No. 226185

Date: 08/11/2002

☐ Jump Start/Changing of battery

☐ Tyre Replacement

☒ Accident/Breakdown

☐ Multi/Basement

☒ With Load/Cargo Box

☐ King Dolly

☐ Transport Charge

☐ Low Body Kit

☐ Door Opening Service

☐ Crane Up/Winch Out

☐ Collect Doc/Key

☐ Repo

☐ Woodlands and Tuas Checkpoint

P# 16101769