



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

-
HFW
30 Raffles Place, #24 01, Singapore 048622
--

Ref: CS/TP22011466/Uwy3

Date: 15/11/2022

Code: TP2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC 7959A	Veh. Inspected	YP 3793U
Policy No.		Coverage (\$)	0.00
Claim No.	HFWSP.FID2086931	Excess (\$)	0.00
Assign From	DARRYL ANDREW QUEK	Assign Date	15/11/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/11/2022	Inspection Date	16/11/2022
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--