



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 64739722



## ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name / Teo Song Cheong Reg No/Reg Date SLN3198C / 19/05/201 Date In/Mileage 11/11/2022/ 0 Chassis No MMBSTA13AHH006052 Engine No 3A92UGB3262 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAK00008	Credit	11/11/2022/ 13:39	BLK	282 / Kevin Leong	28716		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							640 1040.00
RENEW FRONT RH FENDER & AFFECTED AREA							? 520.00
A 33900099							550.00
REPLACE FRT UNDERCARRIAGE PARTS							
E PNT98000							280 160.00
PAINT WORK ON FRT RH FENDER							100 50.00
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
A 10028901							50.00
CHECK WIRING AND ELECTRICAL COMPONENT							
M SUNDRY							20 50.00
REPLACE FRT RH RIM INCLUDING BALANCING							180 120.00
M SUNDRY							
SUNDRIES							
B WHEELALIGNMENT120L							
To Conduct Computerize Full Wheel Alignment				1.00	461.00	23.00	354.97
M STRUT,FR SUSP				1.00	371.00	23.00	285.67
M KNUCKLE,RH				1.00	123.00	23.00	94.71
M BEARING,FR WHEEL HUB				1.00	244.00	23.00	187.88
M HUB ASSY,FR WHEEL				1.00	639.00	23.00	492.03
M FENDER,FR RH				1.00	99.00	23.00	76.23
M SHIELD,FR WHEELHOUSE,RH				1.00	283.00	23.00	217.91
M ARM ASSY,FR SUSP,LWR RH				1.00	834.00	23.00	642.18
M WHEEL,DISC				1.00	25.00	23.00	19.25
M DAMPER,FR SUSP STRUT				1.00	100.00	23.00	77.00
M INSULATOR,FR SUSP STRUT				1.00	27.00	23.00	20.79
M STOPPER,FR SUSP STRUT				1.00	85.00	23.00	65.45
M INSULATOR,FR SUSP STRUT				1.00	17.00	23.00	13.09
M PAD,FR SUSP SPRING				1.00	17.00	00.00	17.00
M EMBLEM ECO							

Estimate

(for CLK)

(Stere CLKK)

Confirm &amp; accepted by

15/11/22, 3:00pm

7% GST on Net 5,004.16  
350.29

Total Payable 5,354.45

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 1