



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011476/Kvy3m4 Date: 02/12/2022 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMZ 4644A	Veh. Inspected	GBD 559K	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS22/1929	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	15/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JTFAT35Y70K203023	Colour	SILVER	
Odometer	224768 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm	
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	2/2 mm	
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	2/2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/11/2022	Inspection Date	16/11/2022	
Survey held at	KAY MOTOR BLK 9 SIN MING INDUSTRIAL ESTATE #01-46 SINGAPORE 575644			
5a. Remarks				
A)REGISTRATION DATE: 22 MAY 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	