

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBR4526E
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2022
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX155 ABS
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G3H6E0017490
Chassis No.:	MH3SG431000013891
Maximum Power Output:	-
Open Market Value:	\$2,551.00
Original Registration Date:	01 Jul 2020
First Registration Date:	01 Jul 2020
Transfer Count:	0
Actual ARF Paid:	\$383.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,439.00
COE Rebate Amount:	\$3,421.00
Total Rebate Amount:	\$3,421.00

The information contained herein is correct as at 16 Nov 2022

OK

Vehicle Type : Scooters

Mileage : -


SGD \$17500

Posted on : 25/10/2022

★ Paid Ad

★ Dealer Ad

Details >

**Yamaha Nmax 155**

Reg Date : 08/12/2020

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 52912km


SGD \$13800

Posted on : 10/10/2022

★ Paid Ad

★ Dealer Ad

Details >

**Yamaha Nmax 155**

Reg Date : 08/03/2021

Capacity : 155cc

Vehicle Type : Scooters

Mileage : -

SGD \$15900

Posted on : 17/09/2022

★ Paid Ad

★ Dealer Ad

Details >

**Yamaha Nmax 155**

Reg Date : 29/11/2021

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 8000km

SGD \$18000

Posted on : 31/10/2022

★ Direct Seller

Details >

**Yamaha Nmax**

Reg Date :

Vehicle Type :

Posted on : 31/10/2022

★ Direct Seller

Details >



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 42092

Customer :

ALLIANZ INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD #09-01
SINGAPORE 068897

DATE : 12/11/2022
CLAIM NO. : 12043
POLICY NO. : MC/00950792/01

ATTN: ALLIANZ INSURANCE SINGAPORE PTE. LTD.

FROM : STEPHANIE

VEHICLE NO : FBR4526E
MAKE/MODEL : YAM / NMAX155 ABS

*Not Action
LEK
P/P &
5 days
Chapman Hui repair
16/11/22*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	Repair	1.00	\$420.00	420.00
2	BALANCER HANDLE P/N: 55166 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$12.00	24.00
3	BEARING 6204 DDU (NSK) P/N: 40237 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
4	BEARING 6301-2NS (NACHI) P/N: 40470 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
5	BEARING 6303 P/N: 29134 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
6	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00
7	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
8	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
9	BOX REAR (YUNMING) ADV47L P/N: 71151 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
10	CLIP COVER (PLASTIC) P/N: 56586 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$6.00	36.00



biSAFE



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2989, (Accounts) + 65 6281 6759

CERT NO: 2000-1-0003
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
11	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	<i>one</i> 27.00 ✓
12	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	<i>one</i> 12.00 ✓
13	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	<i>one</i> 7.00 ✓
14	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	<i>one</i> 12.00 ✓
15	COVER CRANKCASE P/N: 63128 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.00	<i>one</i> 74.00 ✓
16	COVER SIDE LOWER LH (GREY) P/N: 63488 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	<i>one</i> 21.00 ✓
17	COVER SIDE LOWER RH (GREY) P/N: 63490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	<i>one</i> 21.00 X
18	COVER SIDE REAR LH (GREY) P/N: 63497 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	<i>one</i> 28.00 ✓
19	COWLING FRONT LH (GREY) P/N: 63489 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	<i>one</i> 31.00 ✓
20	COWLING FRONT RH (GREY) P/N: 63499 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	<i>one</i> 31.00 X
21	EMBLEM (ABS) P/N: 56578 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	<i>one</i> 32.00 ✓
22	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	<i>one</i> 14.00 ✓
23	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	? 68.00
24	GASKET CLUTCH COVER P/N: 58090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	<i>one</i> 21.00 ✓
25	GEAR DRIVE PRIMARY P/N: 62710 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$77.00	? 77.00
26	GRIP HANDLE LH P/N: 66884 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	<i>one</i> 12.00 X

bizSAFE₃

Quotation Nos. : 42092

S/N	Description	Action	Qty	Unit Price	Amount
27	GRIP HANDLE RH P/N: 67551 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
28	HOUSING CLUTCH P/N: 58135 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
29	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	6.00	\$63.00	378.00
30	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
31	METER IU (12V) NEW MODEL P/N: 34351 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	280.00
32	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
33	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
34	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
35	NUT HOUSING CLUTCH P/N: 64821 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
36	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
37	PLATE CLUTCH FRICTION (AUTO) P/N: 58121 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$119.00	119.00
38	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
39	PROTECTOR EXHAUST P/N: 58086 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
40	SEAL OIL GEAR PRIMARY (21X30X5.5) P/N: 58169 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00
41	SHAFT MAINSTAND P/N: 58180 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00

bizSAFE₃

SUB TOTAL	\$2,992.00
GST @ 7 %	\$209.44
GRAND TOTAL (SGD)	\$3,201.44

Validity: 30 days

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



~~biz~~SAFE



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0983
ISO 9001 : 2015