

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 16 Nov 2022

## **Preliminary Advice**

Vehicle No	: GBL7433B	Accident Date	: 22/07/2022
Make	: TOYOTA HIACE	Policy No.	: DMCVSNW00033502200
Assignment Date	: 15/11/2022	Excess	: S\$2,000.00
Date of Inspection	: 16/11/2022	Est. Duration of Repair	: 28 DAYS
Inspection At	: DING AUTO PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,873.34
Revised Amount	:S\$	26,253.34
Check Items (Estimated)	:S\$	24,590.00
Total	:S\$	50,843.34

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	97,000.00
COE / PARF Rebate	:S\$	35,200.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,800.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part repair.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.