



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

STRIDES AUTOMOTIVE SERVICES PTE LTD

INV No. AC2304951

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV Date 03/08/2023
Reference CS/SMR22011490/Kcy3e2
Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 163Y
Insured Veh. SHC 4870T
Claim No. TAX/11/22/2035
Policy No.
Accident Date 15/11/2022
Inspection Date 16/11/2022

Description	Total
Survey Inspection	128.00
Digital Photographs	
Transportation	
Subtotal	128.00
GST (8%)	10.24
Grand Total	138.24

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011490/Kcy3e2 Date: 03/08/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4870T	Veh. Inspected	SHD 163Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/22/2035	Excess (\$)	0.00	
Assign From	HUE YEN	Assign Date	16/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU503081655	Colour	M.P. WHITE / RED	
Odometer	433167 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WANLI	3 mm	
L/H Front Tyre	195/65 R15	WANLI	3 mm	
R/H Rear Tyre	195/65 R15	SAILUN	4 mm	
L/H Rear Tyre	195/65 R15	SAILUN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/11/2022	Inspection Date	16/11/2022	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 163Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	PANEL SUB-ASSY, FRONT DOOR, LH	BENT	1,300.70	1,300.70
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	SERVICEABLE	193.50	-
1	COVER, FRONT DOOR OUTSIDE HANDLE, LH	SERVICEABLE	17.90	-
1	WEATHERSTRIP, FRONT DOOR, LH	SERVICEABLE	231.30	-
1	HINGE ASSY, FRONT DOOR, LOWER LH	TO REPAIR SEE LABOUR	110.60	-
1	HINGE ASSY, FRONT DOOR, UPPER LH	TO REPAIR SEE LABOUR	97.50	-
1	TAPE, BLACK OUT, NO.1 FRT LH	NECESSARY	13.30	13.30
1	TAPE, BLACK OUT, NO.2 FRT LH	NECESSARY	43.50	43.50
1	TAPE, BLACK OUT, NO.3 FRT LH	NECESSARY	26.30	26.30
1	PANEL SUB-ASSY, REAR DOOR, LH	BENT	1,294.90	1,294.90
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	SERVICEABLE	193.50	-
1	COVER, REAR DOOR OUTSIDE HANDLE, LH	SERVICEABLE	17.90	-
1	HINGE ASSY, REAR DOOR, LOWER LH	TO REPAIR SEE LABOUR	87.10	-
1	HINGE ASSY, REAR DOOR, UPPER LH	TO REPAIR SEE LABOUR	98.90	-
1	TAPE, BLACK OUT, NO.1 REAR LH	NECESSARY	21.90	21.90
1	TAPE, BLACK OUT, NO.2 REAR LH	NECESSARY	34.90	34.90
1	TAPE, BLACK OUT, NO.3 REAR LH	NECESSARY	15.40	15.40
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	SERVICEABLE	926.00	-
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	SERVICEABLE	206.70	-
1	PANEL SUB-ASSY, QUARTER, LH	TO REPAIR SEE LABOUR	871.50	-
1	MOULDING ASSY, BODY ROCKER PANEL, LH	BUCKLED / DENTED	594.80	594.80
1	RIM	DENTED	1,900.10	1,900.10
1	HUBCAP	NO SUCH PARTS	211.50	-
	LESS 25% DISCOUNT		-2,127.43	-1,311.45
			6,382.27	3,934.35
<u>SPECIAL NETT ITEMS</u>				
2	SET DOOR WEATHERSTRIP CLIP (SN)	NOT NECESSARY	130.00	-

Report Ref No. CS/SMR22011490/Kcy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE (SN)	SERVICEABLE	300.00	-
1	FRT DOOR STICKER TRANSCAB (SN)	NECESSARY	100.00	60.00
1	REAR DOOR STICKER TEL. NO (SN)	NECESSARY	100.00	60.00
			630.00	120.00
	LABOUR			
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF HINGE ASSY, FRONT DOOR, LOWER LH, HINGE ASSY, FRONT DOOR, UPPER LH, HINGE ASSY, REAR DOOR, LOWER LH, HINGE ASSY, REAR DOOR, UPPER LH AND PANEL SUB-ASSY, QUARTER, LH.		2,200.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	880.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		240.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		480.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
			5,890.00	1,800.00
GRAND TOTAL			12,902.27	5,854.35

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00
---	--	--	-----------------

Report Ref No. CS/SMR22011490/Kcy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/11/2022 11:41 (SGT)
Reported by	Driver
Date of Accident	15/11/2022 16:38 (SGT)
Exact Location of Accident	Near People's Park Centre B1 Foodcourt, Singapore
Additional Location Information	PEOPLE PARK CENTRE TAXI STAND
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD163Y
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2413997

DRIVER

Name of Driver	PNG YONG TECK
NRIC No	SXXXX425H
Date Of Birth	31/01/1952
Occupation	Outdoor

Police Report
 Cause
 Taxi accident



A: 810165Y

B: 81C4870T

Handwritten signature

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
 Wong Jun Keat

Witnessed by Reporting Centre
 Personnel



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 163Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

