

Not Attached
1/10/2022 & 4700k

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD163Y

AAD2211-071

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

15 NOV 2022

SHD163Y

200303878K

TOYOTA

PRIUS

15/11/2022

SHC4870T/STRIDES

27/6/2019

PART

LIST

1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,300.70	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	193.50	X
1	COVER, FRONT DOOR OUTSIDE HANDLE, LH	\$	17.90	X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	231.30	X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	97.50	X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	13.30	✓
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	43.50	✓
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	193.50	X
1	COVER, REAR DOOR OUTSIDE HANDLE, LH	\$	17.90	X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	98.90	X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	21.90	✓
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	15.40	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	\$	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	206.70	X
1	PANEL SUB-ASSY, QUARTER, LH	\$	871.50	X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80	✓
1	RIM	\$	1,900.10	✓
1	HUBCAP	\$	211.50	X

Trans-cab Auto Services Pte Ltd

AAD2211-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD163Y

TOTAL	\$	8,509.70
25%	\$	2,127.43
	\$	6,382.28

Special Nett

- 2SET DOOR WEATHERSTRIP CLIP
1 TYRE
1 FRT DOOR STICKER TRANSCAB
1 REAR DOOR STICKER TEL. NO

\$	NA	130.00	X
\$	PN	300.00	X
\$	NA	100.00	60%
\$	NA	100.00	60%

TOTAL

\$	630.00
----	--------

TOTAL PARTS	\$	7,012.28
-------------	----	----------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	60%
----	--------	-----

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,200.00	60%
----	----------	-----

Putty And Spray Painting Of The Affected Portion.

\$	2,200.00	88%
----	----------	-----

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	240.00	60%
----	--------	-----

To Check Electrical Lighting Concerned.

\$	170.00	20%
----	--------	-----

To transfer of Door Fittings, attachments and perform water seepage test.

\$	480.00	120%
----	--------	------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD163Y

AAD2211-071

To check steering geometry and computer wheel alignment \$ 220.00 *601*

TOTAL \$ 5,890.00

Over All Total \$ 12,902.28

(LUMP SUM) Repair Days *10 days*

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: