

Not Authored
L/Ping B

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD163Y

AAD2211-071

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 NOV 2022

SHD163Y

200303878K

TOYOTA

PRIUS

15/11/2022

SHC4870T/STRIDES

27/6/2019

PART

LIST

1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,300.70	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	193.50	X
1	COVER, FRONT DOOR OUTSIDE HANDLE, LH	\$	17.90	X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	231.30	X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	97.50	X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	13.30	✓
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	43.50	✓
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	193.50	X
1	COVER, REAR DOOR OUTSIDE HANDLE, LH	\$	17.90	X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	98.90	X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	21.90	✓
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	15.40	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	\$	926.00	?
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	206.70	?
1	PANEL SUB-ASSY, QUARTER, LH	\$	871.50	X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80	✓
1	RIM	\$	1,900.10	✓
1	HUBCAP	\$	211.50	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD163Y**AAD2211-071**

TOTAL	\$	8,509.70
25%	\$	2,127.43
	\$	6,382.28

Special Nett

2SET DOOR WEATHERSTRIP CLIP

\$ *na* 130.00 *X*

1 TYRE

\$ *na* 300.00 *X*

1 FRT DOOR STICKER TRANSCAB

\$ *na* 100.00 *60na*

1 REAR DOOR STICKER TEL. NO

\$ *na* 100.00 *60na***TOTAL****\$ 630.00****TOTAL PARTS \$ 7,012.28****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *601*

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *88a*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *601*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To transfer of Door Fittings, attachments and perform water seepage test.

\$ 480.00 *1201*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD163Y

AAD2211-071

To check steering geometry and computer wheel alignment

\$

220.00

601

TOTAL

\$

5,890.00

Over All Total

\$

12,902.28

(LUMP SUM) Repair Days

10 days

4 days

LOK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/11/2022 11:41 (SGT)
Reported by	Driver
Date of Accident	15/11/2022 16:38 (SGT)
Exact Location of Accident	Near People's Park Centre B1 Foodcourt, Singapore
Additional Location Information	PEOPLE PARK CENTRE TAXI STAND
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD163Y
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2413997

DRIVER

Name of Driver	PNG YONG TECK
NRIC No	SXXXX425H
Date Of Birth	31/01/1952
Occupation	Outdoor

Police Road
Closed
TAXI ON ROAD



A: 810163Y

B: 81C4870T

Handwritten signature

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Wong Jun Keat

Witnessed by Reporting Centre
Personnel