



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|---|--|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR22011491/Uqy3e2 Date: 23/12/2022 Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 6133U | Veh. Inspected | EM 7357Y | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | TAX/11/22/2032 | Excess (\$) | 0.00 | |
| Assign From | HUA YEN | Assign Date | 16/11/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA JAZZ 1.5 (A) | c.c | 1498 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JHMGK5850GX202201 | Colour | YELLOW | |
| Odometer | 58646 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 185/55 R16 | MICHELIN | 7 mm | |
| L/H Front Tyre | 185/55 R16 | MICHELIN | 7 mm | |
| R/H Rear Tyre | 185/55 R16 | MICHELIN | 7 mm | |
| L/H Rear Tyre | 185/55 R16 | MICHELIN | 7 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 14/11/2022 | Inspection Date | 17/11/2022 | |
| Survey held at | KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 9 Working Days | |