## Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541

Tel: 64817221

L H Car Rental Pte Ltd Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541

To putty and spray paint

Check & reconnect wiring.

Vehicle No : SMP 2303 A

Make/Model: Honda Freed

Year

: 2018

Fax: 64816131

Not Notherital
11 Sup & 4250/2
Renny After Paint
4. day

\$1,200.00 6606

\$45.00 201

\$9.024.84

balance c/f

Qty	Description	Unit P	Price Amount	
Estimate (	Cost Of Repair			
1 pc 1 pc 2 pcs 1 pc	Front bonnet lock Front bonnet hinge Front o/s fender Front o/s fender emblem Front support panel Front headlamp Front radiator grille Front radiator grille emblem Front bumper Front bumper reinforcement Front bumper sponge Front bumper side retainer Wiper tank	<i>clsins</i> \$1,4	\$819.00 \$121.70 × \$121.70 × \$210.20 × \$475.30 \$55.70 \$721.50 × \$721.50 × \$75.30 × \$1,014.20 × \$1,014.30 × \$1,01	
S Nett			1	
20 pcs	Front bumper clip	\$2	2.00 Ma \$40.00 C	
Labour Ch	Labour Charges			
Remove/renew the above parts including knocking, welding & cutting. \$1,200.00				

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/a er spray painting
 To display damaged part(s) during resurvey

Third party survey is on a "Without Prejudice" basis

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

· Parts prices are subject to confirmation

No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date:

## SMP 2303 A

balance b/f

\$9,024.84

Labour Charges

To respray anti-rust proofing treatment

Remove/refit air con condenser and to top up gas element.

\$120.00 601

\$180.00 \$9,324.84

Total