

PREMIER@Kaki Bukit, 8 Kaki Bukit Ave 4, #02-03/04 S415875

✓ WORKSHOP ESTIMATE

Date In / Out: 16.11.2022

Invoice No:

Mileage In / Out: _____

Cash Card (Y/N) / Amount: _____

Page No: 1-3

No	Description	Qty	Amount (SGD)
1.	Boattail Assy Bent d	IPC	/ 685.00
2.	Boot Lock Assy Rnd	IPC	- 225.00
3.	Boot Garnish Panel NHE m	IPC	+ 225.00
4.	Boot Seal XH m	IPC	x. 215.00
5.	Lock Striker XH m	IPC	X. 85.00
6.	End Panel Assy Penis	IPC	* 875.00
7.	End Panel Top Garnish Del'd	IPC.	? 195.00
8.	Rr Bumper Assy Del'd	IPC	/ 685.00
9.	Rr Reinforcement Beam Best	IPC.	Z / 365.00
10.	Lr Bumper LH/RH reflector . NHE m	2PCS	x. 95 x 2
11.	Rr LH Tail Lamp - XH m	IPC	x 375.00.
12.	Rr Bumper retainers LH/RH XH m	2PCS.	/ 85 x 2 =
13.	Rr Buzzzer Module c/w	IPC.	/ 135.00
14.			
15.			

2368
Total @ 20% : 1894.40

JOB ORDER

QUOTATION

✓ WORKSHOP ESTIMATE

Name: _____

Date In / Out: _____

Vehicle No: SCP 1311 B

Invoice No: _____

Model / Color: Honda Civic 1.5 A.

Mileage In / Out: _____


Chassis No: _____

Cash Card (Y/N) / Amount: _____

Petrol Level: | F | | | E |

Page No: 2 / 3

[illegible]



✓ WORKSHOP ESTIMATE

Page No: 3/3

No	Description Labour	Qty	Amount (SGD)
1.	Panel Beating Affected Panels		700.00 600
2.	Spray Painting Affected Panels x 30		800.00 600
3.	CHE wiring .		120.00 30
4.	Paint Protection Coating	1 car	980.00 300
5.			
6.			
	Total: 4594.40		Admin C _T
	L/S: 3650.		a/s 16/12/22
	04 Days.		# Number of days ?? 04 Days
	LKK Auto Consultants hence notify the Repairer of the following:		
	• To resurvey before/after spray painting		
	• To display damaged part(s) during resurvey		
	• Parts prices are subject to confirmation		
	• Third party survey is on a "Without Prejudice" basis		
	• No illegal modification(s) is allowed		
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	Acknowledged by Repairer		
	Signature:		
	Date:		