



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/ASM22011497/Upa3q2 Date: 20/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMX 7559D	Veh. Inspected	SJY 6286C
Policy No.	GA570842	Coverage (\$)	0.00
Claim No.	S2M04EZP	Excess (\$)	0.00
Assign From		Assign Date	16/11/2022
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO EX FORTE (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFU411MA5283971	Colour	BLACK / RED
Odometer	164186 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45Z R17	TOURADOR	6 mm
L/H Front Tyre	225/45Z R17	TOURADOR	6 mm
R/H Rear Tyre	225/45Z R17	TOURADOR	6 mm
L/H Rear Tyre	225/45Z R17	TOURADOR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/11/2022	Inspection Date	17/11/2022
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	