

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVENUE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

TP China -
Veron.

Contact : 87420435, 93279300

TAX INVOICE

Repair Code : CLM17477

Date in : 15/11/2022

Vehicle Num. : SNH2550H

Model : TOYOTA YARIS CROSS HYBRID ACTIVE (AT) (2WD)

Chassis/Eng# : JTDKBAB3201001838/M15AY463411

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER (LOWER) <i>Debond</i>	1	525.50	✓ 525.50
REAR BUMPER (TOP)	1	417.10	✓ 417.10
REAR BUMPER LH END SEAL COVER <i>Dehd</i>	1	98.20	✓ 98.20
REAR BUMPER LH REFLECTOR <i>Chkd</i>	1	59.00	✓ 59.00
REAR BUMPER LH REVERSE SENSOR <i>Rehd</i>	1	364.20	250 ✓ 364.20
REAR BUMPER SIDE RETAINER L/R <i>LH Chkd</i>	2	100.40	100.40 200.80
REAR END PANEL <i>Regr</i>	1	696.30	X 696.30
REAR END PANEL INNER TOP GARNISH <i>Atc new</i>	1	218.00	X 218.00
REAR LH FENDER <i>Buckled</i>	1	1217.90	✓ 1,217.90
REAR LH FENDER ARCH GARNISH <i>Distorted</i>	1	185.90	✓ 185.90
REAR LH FENDER INNER AIR VENT <i>Dehd</i>	1	161.25	✓ 161.25
REAR LH FENDER INNER SHIELD <i>Dehd</i>	1	191.20	✓ 191.20
REAR LH FENDER INNER TRIM GARNISH <i>Dehd</i>	1	627.00	✓ 627.00
REAR LH PANEL SENSOR <i>Chkd</i>	1	1603.00	✓ 1,603.00
REAR LH PANEL SENSOR GARNISH BRACKET <i>Chkd</i>	1	67.10	✓ 67.10
REAR LH TAILLAMP <i>Chkd</i>	1	492.50	✓ 492.50
REAR LH TAILLAMP LOWER BRACKET <i>Chkd</i>	1	59.10	✓ 59.10
REAR TAILGATE 'CROSS' EMBLEM <i>Not Nec</i>	1	42.95	X 42.95

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVENUE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435, 93279300

TAX INVOICE

Repair Code : CLM17477

Date in : 15/11/2022

Vehicle Num. : SNH2550H

Model : TOYOTA YARIS CROSS HYBRID ACTIVE (AT) (2WD)

Chassis/Eng# : JTDKBAB3201001838/M15AY463411

REAR TAILGATE 'HYBRID' EMBLEM	<i>Not new</i>	605515	1	47.80	<i>X</i>	47.80
REAR TAILGATE 'YARIS' EMBLEM		454136	1	43.00	<i>X</i>	43.00
Subtotal before discount						7,317.80
Percentage discount 25%						1,829.45
Sub-total 1						5,488.35
REAR BUMPER CLIPS - SET	<i>New</i>		1	50.00	<i>30</i>	50.00
REAR BUMPER LH END SEAL COVER CLIPS - SET	<i>new</i>		1	30.00	<i>10</i>	30.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Not new</i>		1	30.00	<i>X</i>	30.00
REAR END PANEL SEALANT	<i>Not new</i>		1	80.00	<i>X</i>	80.00
REAR LH FENDER ARCH GARNISH CLIPS - SET	<i>new</i>		1	30.00	<i>20</i>	30.00
REAR LH FENDER INNER SHIELD CLIPS - SET	<i>new</i>		1	30.00	<i>20</i>	30.00
REAR LH FENDER INNER TRIM GARNISH CLIPS - SET	<i>new</i>		1	50.00	<i>30</i>	50.00
REAR LH FENDER SEALANT	<i>new</i>		1	80.00	<i>60</i>	80.00
REAR LH TAILLAMP CLIPS - SET	<i>new</i>		1	30.00	<i>10</i>	30.00
Subtotal before discount						410.00
Percentage discount 0%						0.00
Sub-total 2						410.00
Parts-total						5,898.35

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVENUE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435, 93279300

TAX INVOICE

Repair Code : CLM17477

Date in : 15/11/2022

Vehicle Num. : SNH2550H

Model : TOYOTA YARIS CROSS HYBRID ACTIVE (AT) (2WD)

Chassis/Eng# : JTDKBAB3201001838/M15AY463411

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

180. 250.00

60.00

80 100.00

60 140.00

1930 600 1,300.00

900. 1,500.00

50.00

Labour Total

3,400.00

Parts & Labour Total

9,298.35

*** This is a computer-generated document which requires no signature.***

page 3

Adrian L
H/S 26/11/22

06 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6651.36

L/S: 5.3K