



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22011501/Avy3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 16/02/2023

ATTN: RODENIC YUEN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 1778Z	Veh. Inspected	SLR 8938E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1196875-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	16/11/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GP71114183	Colour	BLACK
Odometer	399594 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	GITI	6 mm
L/H Front Tyre	205/50 R16	GITI	6 mm
R/H Rear Tyre	205/50 R16	GITI	6 mm
L/H Rear Tyre	205/50 R16	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/11/2022	Inspect Date / Time	16/11/2022 (01:56 PM)
Survey held at	HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**