

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbb@gmail.com

Tribecar Pte Ltd
51 Ubi Avenue 1, #03-30
Paya Ubi Industrial Park
Singapore 408933

TP INC
Veron

Date of survey: 16 November 2022

Motor surveyor: LKK Auto

Surveyor: Adrian Ling

12th November 2022

Type of repair: Lump Sum

Estimate cost of repairs to Honda Shuttle Hybrid - SLR 8938 E

1 pc	Tailgate <i>Distal d</i>	\$ 1,193.40 ✓
1 pc	Tailgate 'H' emblem <i>free</i>	\$ 33.10 ✓
1 pc	Tailgate 'Hybrid' emblem <i>free</i>	\$ 65.20 ✓
1 pc	Tailgate 'Shuttle' emblem	\$ 55.00 ✓
1 pc	Tailgate moulding <i>Amal d</i>	\$ 95.10 ✓
1 pc	Tailgate weatherstrip <i>cut</i>	\$ 95.10 ✓
1 pc	Tailgate wiper motor <i>2pc</i>	\$ 318.40 ✓
1 pc	Tailgate wiper arm <i>at</i>	\$ 68.30 ✓
1 pc	Tailgate inner lock <i>2pc</i>	\$ 175.10 ✓
1 pc	Tailgate inner trim board <i>Amal d</i>	\$ 619.50 323
2 pcs	Tailgate reflectors @\$380.90 <i>HA at</i>	\$ 761.80 380.90
2 pcs	Rear lamps @\$520.50 <i>HA at</i>	\$ 1,041.00 520.50
1 pc	Rear windscreen <i>Shuttle d</i>	\$ 1,480.40 1210
1 pc	Rear windscreen lower moulding <i>free</i>	\$ 46.50 ✓
1 pc	Rear windscreen upper moulding <i>free</i>	\$ 30.60 ✓
1 pc	Rear end panel <i>Delet</i>	\$ 601.50 ✓
1 pc	Rear end panel centre garnish <i>Delet</i>	\$ 155.60 ✓
1 pc	Rear end panel antenna <i>new</i>	\$ 93.60 +
1 pc	Rear bumper <i>Delet</i>	\$ 1,150.60 985
2 pcs	Rear bumper retainers @\$28.60 <i>new</i>	\$ 57.20 +
		\$ 8,137.00
	Less 20%	\$ 1,627.40
		\$ 6,509.60

6352.30

5081.84

1 set	Tailgate inner trim clips	2 per	\$ 30.00 SN	✓
1 set	Rear bumper clips		\$ 30.00 SN	✓
1 pc	Rear windscreen sealant	per	\$ 40.00 SN	✓
1 set	Reverse sensors	David	\$ 250.00 SN	2w
	To remove and renew rear windscreen glass		\$ 150.00	120
	To remove and refit reverse sensors		\$ 60.00	50
	To remove and refit tailgate interior fittings		\$ 120.00	60
	To remove and refit back-up camera		\$ 50.00	✓
	Labour charges to remove, adjust and renew the above parts etc		\$ 800.00	600
	Tuff kote		\$ 60.00	✓
	Wiring charges	1570	\$ 50.00	30
	Spray painting		\$ 800.00	600
			<u>\$ 8,949.60</u>	

Dollars : Eight thousand nine hundred forty-nine dollars and sixty cents

Adrian L
L/s 16/11/22
06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Supplementary: 421.20

Total: 7373.04

L/s: 5.9k.

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhhib@gmail.com

Tribecar Pte Ltd
51 Ubi Avenue 1, #03-30
Paya Ubi Industrial Park
Singapore 408933

Date of survey: 16 November 2022

Motor surveyor: LKK Auto

Surveyor: Adrian Ling

12th November 2022

Type of repair: **Lump Sum**

Supplementary cost of repairs to Honda Shuttle Hybrid - SLR 8938 E

1 pc Rear bumper reflector sponge LH
Less 20%

auth'd

\$	115.40
\$	23.08
\$	92.32

89.

1 pc Back-up camera

Done

\$	350.00	SN
\$	442.32	

Dollars: Four hundred forty-two dollars and thirty-two cents.

89

less 20% 71.20

SN : 350

Supplementary: 421.20