

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 15.11.2022

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLX7756M**
MODEL : **KIA CARENS**
DATE OF ACCIDENT : 14.11.2022
TIME OF ACCIDENT : 15:05 HRS

Xiao Chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 695.00	\$ 695.00
2	FRONT BUMPER LOGO <i>New</i>	1	\$ 76.00	\$ 76.00
3	FRONT BUMPER SIDE RETAINER <i>24 Pcs</i>	2	\$ 19.00	\$ 38.00
5	FRONT BUMPER CENTER SUPPORT BRACKET <i>new</i>	1	\$ 89.00	\$ 89.00
6	FRONT BUMPER SIDE BRACKET <i>new</i>	2	\$ 36.00	\$ 72.00
7	FRONT BUMPER SENSOR LH <i>new</i>	2	\$ 188.60	\$ 377.20
8	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 186.00	\$ 186.00
9	FRONT BUMPER LOWER GRILLE COVER <i>new</i>	1	\$ 98.00	\$ 98.00
10	FRONT CENTRE GRILLE <i>new</i>	1	\$ 356.00	\$ 356.00
11	FRONT FOG LAMP LH <i>Replaced</i>	1	\$ 247.00	\$ 247.00
12	FRONT FOG LAMP COVER LH <i>Replaced</i>	1	\$ 156.00	\$ 156.00
13	FRONT FENDER LH <i>Distorted</i>	1	\$ 545.00	\$ 545.00
14	FRONT FENDER COWLING LH <i>torn</i>	1	\$ 186.00	\$ 186.00
18	FRONT DOOR VIEW MIRROR LH <i>new</i>	1	\$ 765.00	\$ 765.00
21	FRONT SUPPORT PANEL <i>Replaced</i>	1	\$ 728.00	\$ 728.00
22	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 105.00	\$ 105.00
23	HEADLAMP LH <i>Replaced</i>	1	\$ 1,558.00	\$ 1,558.00
24	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 56.00	\$ 112.00
25	FRONT WHEEL RIM LH <i>cut</i>	1	\$ 774.00	\$ 774.00
26	FRONT ABS SENSOR <i>new</i>	1	\$ 164.00	\$ 164.00

4500

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLX7756M**
 MODEL : **KIA CARENS**
 DATE OF ACCIDENT : 14.11.2022
 TIME OF ACCIDENT : 15:05 HRS

27	FRONT KNUCKLE ARM LH <i>Brkd</i>	1	\$	456.00	\$	456.00	<i>✓</i>
28	FRONT WHEEL BEARING LH <i>Brkd</i>	1	\$	268.00	\$	268.00	<i>✓</i>
29	FRONT WHEEL HUP LH <i>Brkd</i>	1	\$	302.00	\$	302.00	<i>✓</i>
30	FRONT SHOCK ABSORBER LH <i>Brkd</i>	1	\$	425.00	\$	425.00	<i>✓</i>
31	FRONT LOWER ARM LH <i>Brkd</i>	1	\$	543.00	\$	543.00	<i>✓</i>
32	FRONT STEERING RACK AND PINION <i>new</i>	1	\$	1,106.00	\$	1,106.00	<i>✓</i>

6076

5468.40

S.N: 450

TOTAL PRICE \$ 10,427.20
 LESS 10% \$ 1,042.72
SUB TOTAL PRICE \$ 9,384.48

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT SUPPORT PANEL TOP GARNISH CLIP <i>new</i>	1	\$ 50.00	\$ 50.00
4	FRONT CENTER GRILLE CLIP (SET) <i>3 x 1</i>	1	\$ 50.00	\$ 50.00
5	FRONT LOWER GRILLE CLIP (SET) <i>1 x 1</i>	1	\$ 50.00	\$ 50.00
6	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
7	COOLANT <i>new</i>	1	\$ 80.00	\$ 80.00
8	BRAKE OIL <i>new</i>	1	\$ 50.00	\$ 50.00

1000

TOTAL \$ 420.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD , CUT, ADJUST, KNOCK	\$ 1,400.00	800
2	TO SPRAY PAINT	\$ 1,000.00	400
3	TUFF COAT	\$ 250.00	40
4	WIRING, BULB CHECKING	\$ 180.00	30
5	REMOVE AND REFIX HEADLAMP	\$ 80.00	X

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLX7756M**
MODEL : **KIA CARENS**
DATE OF ACCIDENT : 14.11.2022
TIME OF ACCIDENT : 15:05 HRS

6	REMOVE AND REFIX AIR-CON CONDENSER	\$ 120.00	60
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	320
8	FOUR WHEEL ALIGNMNET	\$ 120.00	80
9	REMOVE AND REFIX RADIATOR	\$ 100.00	60
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,804.48
TOTAL LABOUR COST : \$ 4,080.00
TOTAL REPAIR COST : \$ 13,884.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
w/s 16/11/22
08 Days.

Total: 770840

w/s: 6150 ✓

1690