

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM BOON HWEE
 BLK 449 BUKIT PANJANG RING ROAD
 #06-579
 SINGAPORE 670449

Contact : 96737200

TAX INVOICE

Repair Code : CLM17473
 Date in : 14/11/2022
 Vehicle Num. : SKV5904M
 Model : TOYOTA WISH 1.8 CVT
 Chassis/Eng# : JTDGG20W70J002784/2ZR1593025

TP Allianz
 Xiao Boy

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>del</i>	1	698.10	✓ 698.10
REAR BUMPER BRACKET L/R <i>del</i> <i>del</i> <i>del</i>	2	55.00	✓ 110.00
REAR BUMPER REFLECTOR L/R <i>del</i>	2	95.00	✓ 190.00
REAR BUMPER REVERSE SENSOR <i>del</i>	2	189.00	✓ 378.00
REAR BUMPER SIDE BRACKET L/R <i>del</i>	2	55.00	✓ 110.00
REAR BUMPER SIDE RETAINER L/R <i>del</i>	2	141.45	✓ 282.90
REAR END PANEL <i>del</i>	1	540.80	✓ 540.80
REAR END PANEL ANTENNA SENSOR <i>del</i>	1	138.50	✓ 138.50
REAR END PANEL INNER TOP GARNISH <i>del</i>	1	285.00	✓ 285.00
REAR FENDER INNER SHIELD L/R <i>del</i>	2	87.00	✓ 174.00
REAR FENDER INNER TRIM BOARD L/R <i>del</i>	2	480.10	✓ 960.20
REAR FLOOR PANEL <i>del</i>	1	680.10	✓ 680.10
REAR FLOOR PANEL CARPET <i>del</i>	1	380.70	✓ 380.70
REAR FLOOR PANEL END PANEL <i>del</i>	1	305.70	✓ 305.70
REAR FLOOR PANEL SIDE BOARD COVER L/R <i>del</i>	2	267.30	✓ 534.60
REAR FLOOR PANEL TOP BOARD COVER <i>del</i>	1	498.70	✓ 498.70
REAR FLOOR PANEL TOP GARNISH <i>del</i>	1	213.10	✓ 213.10
REAR SPARE TYRE CARRIAGE <i>del</i>	1	328.70	✓ 328.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM BOON HWEE
BLK 449 BUKIT PANJANG RING ROAD
#06-579
SINGAPORE 670449

Contact : 96737200

TAX INVOICE

Repair Code : CLM17473

Date in : 14/11/2022

Vehicle Num. : SKV5904M

Model : TOYOTA WISH 1.8 CVT

Chassis/Eng# : JTDGG20W70J002784/2ZR1593025

REAR TAILGATE <i>Distorted</i>	1	1515.00	<i>1309-</i> 1515.00
REAR TAILGATE 'LOGO' EMBLEM <i>me</i>	1	72.50	✓ 72.50
REAR TAILGATE DAMPER L/R <i>3 mea</i>	2	299.10	+ 598.20
REAR TAILGATE HINGES L/R	2	68.10	+ 136.20
REAR TAILGATE INNER PULL HANDLE <i>mea</i>	1	131.20	+ 131.20
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>mea</i>	2	35.10	+ 70.20
REAR TAILGATE INNER SIDE GARNISH L/R <i>mea</i>	2	138.00	+ 276.00
REAR TAILGATE INNER TOP GARNISH <i>cut</i>	1	148.00	✓ 148.00
REAR TAILGATE INNER TRIM BOARD <i>cut</i>	1	508.10	✓ 508.10
REAR TAILGATE LOCK STRIKER <i>mea</i>	1	48.30	+ 48.30
REAR TAILGATE MECHANISM LOCK <i>2 mea</i>	1	517.10	✓ 517.10
REAR TAILGATE NUMBER PLATE LAMP L/R <i>mea</i>	2	69.10	+ 138.20
REAR TAILGATE OUTER CHROME HANDLE <i>cut</i>	1	236.10	✓ 236.10
REAR TAILGATE OUTER LOCK SWITCH <i>mea</i>	1	110.35	+ 110.35
REAR TAILGATE REFLECTOR INNER BLACK GASKET L/R <i>me</i>	2	35.50	<i>40</i> 71.00
REAR TAILGATE REFLECTOR L/R <i>cut</i>	2	308.30	✓ 616.60
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	320.00	✓ 320.00
REAR TAILGATE WINDSCREEN <i>cut</i>	1	1131.90	✓ 1,131.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM BOON HWEE
BLK 449 BUKIT PANJANG RING ROAD
#06-579
SINGAPORE 670449

Contact : 96737200

TAX INVOICE

Repair Code : CLM17473
Date in : 14/11/2022
Vehicle Num. : SKV5904M
Model : TOYOTA WISH 1.8 CVT
Chassis/Eng# : JTDGG20W70J002784/2ZR1593025

REAR TAILGATE WINDSCREEN MOULDING <i>Ne</i>	1	110.35	✓	110.35
REAR TAILGATE WIPER ARM <i>ut</i>	1	161.45	✓	161.45
REAR TAILGATE WIPER ARM COVER <i>Neu</i>	1	131.35	+	131.35
REAR TAILGATE WIPER MOTOR <i>Dang d</i>	1	689.55	385	689.55
REAR TAILLAMP L/R <i>Cached.</i>	2	524.00	868	1,048.00
Subtotal before discount				15,594.75
Percentage discount 25%				3,898.69
Sub-total 1				11,696.06
REAR BUMPER CLIPS - SET <i>Ne</i>	1	80.00	30	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Ne</i>	1	40.00	20	40.00
REAR FENDER INNER SHIELD CLIPS L/R - SET <i>Ne u</i>	2	25.00	+	50.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>Ne</i>	2	50.00	60	100.00
REAR FLOOR PANEL INSULATOR MAT <i>Ne a</i>	1	300.00	+	300.00
REAR TAILGATE CAMERA <i>Ne u</i>	1	800.00	+	800.00
REAR TAILGATE INNER SIDE GARNISH CLIPS L/R - SET <i>Ne u</i>	2	25.00	+	50.00
REAR TAILGATE INNER TOP GARNISH CLIPS - SET <i>Ne</i>	1	25.00	10	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Ne</i>	1	50.00	30	50.00
REAR TAILGATE NUMBER PLATE <i>Best</i>	1	25.00	✓	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LIM BOON HWEE
 BLK 449 BUKIT PANJANG RING ROAD
 #06-579
 SINGAPORE 670449

Contact : 96737200

TAX INVOICE

Repair Code : CLM17473

Date in : 14/11/2022

Vehicle Num. : SKV5904M

Model : TOYOTA WISH 1.8 CVT

Chassis/Eng# : JTDGG20W70J002784/2ZR1593025

REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	30	50.00
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	1	30.00	20	30.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	30	80.00
REAR TAILGATE WINDSCREEN SOLAR FILM	1	250.00	200	250.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	20	40.00
Subtotal before discount				1,970.00
Percentage discount 0%				0.00
Sub-total 2				1,970.00
Parts-total				13,666.06

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

80.00

120 150.00

80 100.00

80 1,200.00

80 1,000.00

60 120.00

80.00

2,730.00

16,396.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts/using resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 4

Adrian L
 A/S 16/11/22

obhys

total: 10491.57

A/S: 8.31C ✓