

11/17/22, 2:28 PM

Repairer Estimates

Auto Insure Pte Ltd (HQ) (Co.Reg.No.201437380M)

6 Marsiling Lane
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	M6790
Policy No:	SP2003053801	Date of Loss:	11/11/2022
Vehicle Reg. No.:	SMF5800P	Driveable?	NO
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANDREW KOH		

Make/Model:	BMW 328i, 2.0 D/AB 4DR ABS HID NAV (A)	Vehicle Reg. Date:	29/03/2012
Vehicle Colour:	METALLIC DARK GREY	Gen Condition:	FAIR
Engine No:	A3950122N20B20A	Chassis No:	WBA3A52000F253608
Odometer:	118397 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	10		

*Not Authorised
Returning BY Paint
Ex \$1100/*

Present Location: AUTO INSURE PTE LTD (HQ) (WOODLANDS)

COST OF CLAIMS

Amount

Parts	30,607.50
Miscellaneous Items	190.00
Labour	1,600.00
Paintwork Labour	1,200.00
Towing	0.00

Calculated Gross Total (S\$)	33,597.50
- Excess (S\$)	600.00
(S\$)	32,997.50
+ GST 7.00% (S\$)	2,309.83
Nett Amount (S\$)	35,307.33

This claim is handled by: MARVYN CHUA HONG LENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11/17/22, 2:28 PM

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2022)
 Parts: 143 BMW 328I 2.0 D/AB 4DR ABS HID NAV (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR INTAKE GRILLE	0.00	0.00	CM *25.00 F ✓
2	1		*AIR INTAKE TUBE	0.00	0.00	CM *45.00 F ✓
3	1		*AIR OUTLET HOSE	0.00	0.00	DIY *75.00 F ✓
4	1		*AIR TUBE	0.00	0.00	DIY *110.00 F ✓
5	1		*BONNET	0.00	0.00	Bu *1,620.00 F ✓
6	1		*BONNET ADJUSTER	0.00	0.00	DIY *15.00 F ✓
7	1		*BONNET FRT GASKET	0.00	0.00	DIY *50.00 F ✓
8	1		*COMPR/CONDENSER PIPE	0.00	0.00	*235.00 F ?
9	1		*COND/EVAPORATOR PIPE	0.00	0.00	*385.00 F ?
10	1		*CONDENSER	0.00	0.00	Pu *1,320.00 F ✓
11	1		*CTR FRT BUMP SUPPORT	0.00	0.00	DIY *25.00 F ✓
12	1		*CTR INTAKE CHANNEL	0.00	0.00	*70.00 F ?
13	1		*ELECTRIC FAN COMPLETE	0.00	0.00	*1,670.00 F ?
14	1		*EXPANSION TANK	0.00	0.00	CM *150.00 F ✓
15	1		*EXPANSION TANK CAP	0.00	0.00	DIY *30.00 F X
16	1		*FRONT BUMPER TRIM	0.00	0.00	CM *960.00 F ✓
17	1		*FRONT PANEL SUPPORT	0.00	0.00	*165.00 F ?
18	1		*FRT BUMPER AIR GRILLE	0.00	0.00	*170.00 F ?
19	1		*FRT CONNECTING STRUT	0.00	0.00	Bu *240.00 F ✓
20	1		*FRT CTR BUMPER TRIM	0.00	0.00	CM *45.00 F ✓
21	1		*FRT LOWER AIR GUIDE	0.00	0.00	*145.00 F ?
22	1		*FRT LWR BUMPER CARR	0.00	0.00	*180.00 F ?
23	1		*FRT TOWING EYE COVER	0.00	0.00	Pu *40.00 F X
24	1		*FRT UPPER BUMPER CARR	0.00	0.00	*400.00 F ?
25	1		*FRT UPPER AIR GUIDE	0.00	0.00	CM *250.00 F ✓
26	1		*FRT UPP IMPACT DAMP	0.00	0.00	*90.00 F ?
27	1		*FUEL PUMP	0.00	0.00	*590.00 F ?
28	1		*GRILLE BADGE	0.00	0.00	DIY *90.00 F ✓
29	1		*HIGH TONE HORN	0.00	0.00	*130.00 F ?
30	1		*INTAKE CHANNEL	0.00	0.00	*75.00 F ?
31	1		*INTERCOOLER	0.00	0.00	*830.00 F ?
32	1		*L/AIR COOLER HOSE	0.00	0.00	*540.00 F ?
33	1		*L/AIR INTAKE TRIM	0.00	0.00	*105.00 F ?
34	1		*R/BRAKE AIR GUIDE	0.00	0.00	*70.00 F ?
35	1		*R/BUMPER AIR GUIDE	0.00	0.00	*85.00 F ?
36	1		*R/F ADAPTER PLATE	0.00	0.00	*90.00 F ?
37	1		*R/F BONNET STRUT	0.00	0.00	*165.00 F ?
38	1		*R/F BUMPER SUPPORT	0.00	0.00	*15.00 F ?
39	1		*R/F CTR S/PANEL BRKT	0.00	0.00	*55.00 F ?
40	1		*R/F DEFORMATION ELEM	0.00	0.00	*135.00 F ?
41	1		*R/F GRILLE	0.00	0.00	DIY *170.00 F ✓
42	1		*R/F INNER SUPPORT	0.00	0.00	*230.00 F ?
43	1		*R/F LIP	0.00	0.00	*90.00 F ?
44	1		*R/F LWR DAMPER	0.00	0.00	*20.00 F ?
45	1		*R/F LWR DEFORM ELEM	0.00	0.00	*115.00 F ?

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

11/17/22, 2:28 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*R/F LWR S/PANEL BRKT	0.00	0.00	
47	1		*R/FOG LAMP CARRIER	0.00	0.00	*50.00 F ?
48	1		*R/F PANEL SUPPORT	0.00	0.00	*70.00 F ?
49	1		*R/F SUPPORT MEMBER	0.00	0.00	*140.00 F ?
50	1		*R/F SUSPN BUFFER	0.00	0.00	*255.00 F ?
51	1		*R/F UPP S/PANEL BRKT	0.00	0.00	*20.00 F ?
52	1		*R/F WASHER JET	0.00	0.00	*30.00 F ?
53	1		*R/F WHEELHOUSE COVER	0.00	0.00	*210.00 F ?
54	1		*R/F WHEEL HOUSE COVER CAP	0.00	0.00	*160.00 F X
55	1		*R/F W-HOUSE RR COVER	0.00	0.00	*20.00 F X
56	1		*R/F WING	0.00	0.00	*160.00 F X
57	1		*R/GAS DISCHARGE LAMP	0.00	0.00	*600.00 F X
58	1		*R/LOCK COVER	0.00	0.00	*340.00 F ?
59	1		*R/LWR RADIATOR BRACKET	0.00	0.00	*35.00 F ?
60	1		*R/LWR RADIATOR BRACKET	0.00	0.00	*80.00 F ?
61	1		*R/RADIATOR BRACKET	0.00	0.00	*40.00 F ?
62	1		*R/TORSION CONTROL	0.00	0.00	*105.00 F ?
63	1		*R/UPPER LOCK	0.00	0.00	*15.00 F ?
64	1		*R/UPPER HEADLAMP BRKT	0.00	0.00	*40.00 F ?
65	1		*R/UPP RADIATOR BRKT	0.00	0.00	*30.00 F ?
66	1		*R/UPP RADIATOR HOSE	0.00	0.00	*30.00 F ?
67	1		*R/WASHER NOZZEL TRIM	0.00	0.00	*80.00 F ?
68	1		*RADIATOR	0.00	0.00	*60.00 F X
69	1		*RAD-SHROUD UPP SEAL	0.00	0.00	*1,035.00 F ?
70	1		*REAR LAMP HEATER HOSE	0.00	0.00	*50.00 F ?
71	1		*RIGHT HEADLAMP ASSY	0.00	0.00	*60.00 F ?
72	1		*R LED-MODUL SET	0.00	0.00	*2,640.00 F ?
73	1		*SOUND INSULATION	0.00	0.00	*290.00 F ?
74	1		*SUCTION LINE	0.00	0.00	*240.00 F ?
75	1		*TEMPERATURE SENSOR	0.00	0.00	*315.00 F ?
76	1		*WATER HOSE	0.00	0.00	*100.00 F ?
77	1		*L/BONNET HINGE	0.00	0.00	*105.00 F ?
78	1		*L/BONNET LOCK	0.00	0.00	*110.00 F ?
79	1		*L/BRAKE AIR GUIDE	0.00	0.00	*70.00 F ?
80	1		*L/BUMPER AIR GRILLE	0.00	0.00	*85.00 F ?
81	1		*L/F ADAPTER PLATE	0.00	0.00	*90.00 F ?
82	1		*L/F BONNET STRUT	0.00	0.00	*190.00 F ?
83	1		*L/F BUMPER SUPPORT	0.00	0.00	*15.00 F ?
84	1		*L/F CTR S/PANEL BRKT	0.00	0.00	*55.00 F ?
85	1		*L/F DEFORMATION ELEM	0.00	0.00	*135.00 F ?
86	1		*L/F GRILLE	0.00	0.00	*170.00 F ?
87	1		*L/F INNER SUPPORT	0.00	0.00	*230.00 F ?
88	1		*L/F LIP	0.00	0.00	*90.00 F ?
89	1		*L/F LWR DAMPER	0.00	0.00	*20.00 F ?
90	1		*L/F LWR DEFORM ELEM	0.00	0.00	*115.00 F ?
91	1		*L/F LWR S/PANEL BRKT	0.00	0.00	*50.00 F ?
92	1		*L/FOG LAMP CARRIER	0.00	0.00	*70.00 F ?
93	1		*L/F PANEL SUPPORT	0.00	0.00	*140.00 F ?
94	1		*L/F SUPPORT MEMBER	0.00	0.00	*255.00 F ?
95	1		*L/F SUSPN BUFFER	0.00	0.00	*20.00 F ?
96	1		*L/F UPP S/PANEL BRKT	0.00	0.00	*30.00 F ?
97	1		*L/F WASHER JET	0.00	0.00	*210.00 F ?
98	1		*L/F WHEELHOUSE COVER CAP	0.00	0.00	*20.00 F ?
99	1		*L/F WHEELHOUSE COVER	0.00	0.00	*160.00 F ?
100	1		*L/F W-HOUSE RR COVER	0.00	0.00	*160.00 F ?
101	1		*L/F WING	0.00	0.00	*600.00 F ?
102	1		*L/GAS DISCHARGE LAMP	0.00	0.00	*340.00 F ?
103	1		*L/LOCK COVER	0.00	0.00	*35.00 F ?
104	1		*L/LWR RADIATOR BRKT	0.00	0.00	*80.00 F ?

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Generated using Merimen e-Claims IEAS
3/5

11/17/22, 2:28 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
105	1		*L/LWR RADIATOR BRKT	0.00	0.00	*40.00 F ?
106	1		*L/LWR RADIATOR HOSE	0.00	0.00	*130.00 F ?
107	1		*L/OIL COOLER HOSE	0.00	0.00	*90.00 F ?
108	1		*L/RADIATOR BRACKET	0.00	0.00	*110.00 F ?
109	1		*L/TORSION CONTROL	0.00	0.00	*15.00 F ?
110	1		*L/UPPER LOCK	0.00	0.00	*40.00 F ?
111	1		*L/UPPER HEADLAMP BRKT	0.00	0.00	*30.00 F ?
112	1		*L/UPPER RADIATOR BRKT	0.00	0.00	*80.00 F ?
113	1		*L/UPPER RADIATOR HOSE	0.00	0.00	*110.00 F ?
114	1		*L/WASHER NOZZEL TRIM	0.00	0.00	*60.00 F ?
115	1		*LEFT HEADLAMP ASSY	0.00	0.00	*2,640.00 F ?
116	1		*L LED-MODUL SET	0.00	0.00	*290.00 F ?
117	1		*LOW TONE HORN	0.00	0.00	*130.00 F ?
118	1		*LWR EXPANS TANK HOSE	0.00	0.00	*90.00 F ?
119	1		*OUTLET HEATER HOSE	0.00	0.00	*70.00 F ?
120	1		*R/AIR COOLER HOSE	0.00	0.00	*420.00 F ?
121	1		*R/AIR INTAKE TRIM	0.00	0.00	*100.00 F ?
122	1		*R/BONNET HINGE	0.00	0.00	*105.00 F ?
123	1		*R/BONNET LOCK	0.00	0.00	*110.00 F ?

F=Franchise part.

Sub Total (\$\$)

27,825.00

+ Margin on L,N Items 10.00% (\$\$)

2,782.50

Total Parts (\$\$)

30,607.50

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

11/17/22, 2:28 PM

Repairer Estimates

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	AIRCON GAS	60.00
2	1	FRONT BUMPER RIVET & CLIPS	100.00
3	1	RADIATOR COOLANT	30.00
Sub Total (S\$)			190.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR FOR SPRAY PAINTING	New	1,200.00
<u>Labour Items</u>			
2	LABOUR FOR PANEL BEATING	New	1,200.00
3	LABOUR TO REMOVE & REFIT AIRCON CONDENSER	New	200.00
4	LABOUR FOR CHECKING WIRING SYSTEM FOR PROPER FUNCTION	New	200.00
Gross Labour Cost (S\$)			2,800.00

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: