

ASS. REC. BY:

REF:

ALU

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8125K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10/31

Date:

Person Contacted:

Vehicle: IN / OUT

Merida

Veh No:

SMI-5800P

Yr Regn:

03, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 328i

c.c

1997

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

118397

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA3A5200F253608

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/45R18

R:

255/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

11/4/22

D.O.I.

17/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ + RS. SI

) Points

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

11/17/22, 2:28 PM

Repairer Estimates

Auto Insure Pte Ltd (HQ) (Co.Reg.No:201437380M)

6 Marsiling Lane

Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims@autoinsure.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	M6790
Policy No:	SP2003053801	Date of Loss:	11/11/2022
Vehicle Reg. No.:	SMF5800P	Driveable?	NO
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANDREW KOH		

Make/Model:	BMW 328i, 2.0 D/AB 4DR ABS HID NAV (A)	Vehicle Reg. Date:	29/03/2012
Vehicle Colour:	METALLIC DARK GREY	Gen Condition:	FAIR
Engine No:	A3950122N20B20A	Chassis No:	WBA3A52000F253608
Odometer:	118397 KM		

Paint Type:	METALLIC 2K
Total Loss?	NO
Est. Duration of Repair (day)	10

*Not Authorised
Repairing BY paint
Ex \$1100/*

Present Location: **AUTO INSURE PTE LTD (HQ) (WOODLANDS)****COST OF CLAIMS****Amount**

Parts	30,607.50
Miscellaneous Items	190.00
Labour	1,600.00
Paintwork Labour	1,200.00
Towing	0.00

Calculated Gross Total (S\$) **33,597.50****- Excess (S\$)** **600.00****(S\$)** **32,997.50****+ GST 7.00% (S\$)** **2,309.83****Nett Amount (S\$)** **35,307.33****This claim is handled by: MARVYN CHUA HONG LENG**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

11/17/22, 2:28 PM

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2022)
 Parts: 143 BMW 328I 2.0 D/AB 4DR ABS HID NAV (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR INTAKE GRILLE	0.00	0.00	CM *25.00 F ✓
2	1		*AIR INTAKE TUBE	0.00	0.00	CM *45.00 F ✓
3	1		*AIR OUTLET HOSE	0.00	0.00	Dir *75.00 F ✓
4	1		*AIR TUBE	0.00	0.00	Dir *110.00 F ✓
5	1		*BONNET	0.00	0.00	Bu *1,620.00 F ✓
6	1		*BONNET ADJUSTER	0.00	0.00	Dir *15.00 F ✓
7	1		*BONNET FRT GASKET	0.00	0.00	bu *50.00 F ✓
8	1		*COMPR/CONDENSER PIPE	0.00	0.00	*235.00 F ?
9	1		*COND/EVAPORATOR PIPE	0.00	0.00	*385.00 F ?
10	1		*CONDENSER	0.00	0.00	Bu *1,320.00 F ✓
11	1		*CTR FRT BUMP SUPPORT	0.00	0.00	Dir *25.00 F ✓
12	1		*CTR INTAKE CHANNEL	0.00	0.00	*70.00 F ?
13	1		*ELECTRIC FAN COMPLETE	0.00	0.00	*1,670.00 F ?
14	1		*EXPANSION TANK	0.00	0.00	CM *150.00 F ✓
15	1		*EXPANSION TANK CAP	0.00	0.00	bu *30.00 F X
16	1		*FRONT BUMPER TRIM	0.00	0.00	CM *960.00 F ✓
17	1		*FRONT PANEL SUPPORT	0.00	0.00	*165.00 F ?
18	1		*FRT BUMPER AIR GRILLE	0.00	0.00	*170.00 F ?
19	1		*FRT CONNECTING STRUT	0.00	0.00	Bu *240.00 F ✓
20	1		*FRT CTR BUMPER TRIM	0.00	0.00	CM *45.00 F ✓
21	1		*FRT LOWER AIR GUIDE	0.00	0.00	*145.00 F ?
22	1		*FRT LWR BUMPER CARR	0.00	0.00	*180.00 F ?
23	1		*FRT TOWING EYE COVER	0.00	0.00	Bu *40.00 F X
24	1		*FRT UPPER BUMPER CARR	0.00	0.00	*400.00 F ?
25	1		*FRT UPPER AIR GUIDE	0.00	0.00	CM *250.00 F ✓
26	1		*FRT UPP IMPACT DAMP	0.00	0.00	*90.00 F ?
27	1		*FUEL PUMP	0.00	0.00	*590.00 F ?
28	1		*GRILLE BADGE	0.00	0.00	Bu *90.00 F ✓
29	1		*HIGH TONE HORN	0.00	0.00	*130.00 F ?
30	1		*INTAKE CHANNEL	0.00	0.00	*75.00 F ?
31	1		*INTERCOOLER	0.00	0.00	*830.00 F ?
32	1		*L/AIR COOLER HOSE	0.00	0.00	*540.00 F ?
33	1		*L/AIR INTAKE TRIM	0.00	0.00	*105.00 F ?
34	1		*R/BRAKE AIR GUIDE	0.00	0.00	*70.00 F ?
35	1		*R/BUMPER AIR GUIDE	0.00	0.00	*85.00 F ?
36	1		*R/F ADAPTER PLATE	0.00	0.00	*90.00 F ?
37	1		*R/F BONNET STRUT	0.00	0.00	*165.00 F ?
38	1		*R/F BUMPER SUPPORT	0.00	0.00	*15.00 F ?
39	1		*R/F CTR S/PANEL BRKT	0.00	0.00	*55.00 F ?
40	1		*R/F DEFORMATION ELEM	0.00	0.00	*135.00 F ?
41	1		*R/F GRILLE	0.00	0.00	Dir *170.00 F ✓
42	1		*R/F INNER SUPPORT	0.00	0.00	*230.00 F ?
43	1		*R/F LIP	0.00	0.00	*90.00 F ?
44	1		*R/F LWR DAMPER	0.00	0.00	*20.00 F ?
45	1		*R/F LWR DEFORM ELEM	0.00	0.00	*115.00 F ?

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

11/17/22, 2:28 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*R/F LWR S/PANEL BRKT	0.00	0.00	
47	1		*R/FOG LAMP CARRIER	0.00	0.00	*50.00 F ?
48	1		*R/F PANEL SUPPORT	0.00	0.00	*70.00 F ?
49	1		*R/F SUPPORT MEMBER	0.00	0.00	*140.00 F ?
50	1		*R/F SUSPN BUFFER	0.00	0.00	*255.00 F ?
51	1		*R/F UPP S/PANEL BRKT	0.00	0.00	*20.00 F ?
52	1		*R/F WASHER JET	0.00	0.00	*30.00 F ?
53	1		*R/F WHEELHOUSE COVER	0.00	0.00	*210.00 F ?
54	1		*R/F WHEEL HOUSE COVER CAP	0.00	0.00	*160.00 F ✓
55	1		*R/F W-HOUSE RR COVER	0.00	0.00	*20.00 F X
56	1		*R/F WING	0.00	0.00	*160.00 F X
57	1		*R/GAS DISCHARGE LAMP	0.00	0.00	*600.00 F X
58	1		*R/LOCK COVER	0.00	0.00	*340.00 F ?
59	1		*R/LWR RADIATOR BRACKET	0.00	0.00	*35.00 F ✓
60	1		*R/LWR RADIATOR BRACKET	0.00	0.00	*80.00 F ?
61	1		*R/RADIATOR BRACKET	0.00	0.00	*40.00 F ?
62	1		*R/TORSION CONTROL	0.00	0.00	*105.00 F ?
63	1		*R/UPPER LOCK	0.00	0.00	*15.00 F ?
64	1		*R/UPPER HEADLAMP BRKT	0.00	0.00	*40.00 F ✓
65	1		*R/UPP RADIATOR BRKT	0.00	0.00	*30.00 F ✓
66	1		*R/UPP RADIATOR HOSE	0.00	0.00	*30.00 F ?
67	1		*R/WASHER NOZZEL TRIM	0.00	0.00	*80.00 F ?
68	1		*RADIATOR	0.00	0.00	*60.00 F X
69	1		*RAD-SHROUD UPP SEAL	0.00	0.00	*1,035.00 F ?
70	1		*REAR LAMP HEATER HOSE	0.00	0.00	*50.00 F ?
71	1		*RIGHT HEADLAMP ASSY	0.00	0.00	*60.00 F ?
72	1		*R LED-MODUL SET	0.00	0.00	*2,640.00 F ✓
73	1		*SOUND INSULATION	0.00	0.00	*290.00 F ?
74	1		*SUCTION LINE	0.00	0.00	*240.00 F ✓
75	1		*TEMPERATURE SENSOR	0.00	0.00	*315.00 F ?
76	1		*WATER HOSE	0.00	0.00	*100.00 F ?
77	1		*L/BONNET HINGE	0.00	0.00	*105.00 F ?
78	1		*L/BONNET LOCK	0.00	0.00	*105.00 F ?
79	1		*L/BRAKE AIR GUIDE	0.00	0.00	*110.00 F ✓
80	1		*L/BUMPER AIR GRILLE	0.00	0.00	*70.00 F ?
81	1		*L/F ADAPTER PLATE	0.00	0.00	*85.00 F ?
82	1		*L/F BONNET STRUT	0.00	0.00	*90.00 F ?
83	1		*L/F BUMPER SUPPORT	0.00	0.00	*190.00 F ?
84	1		*L/F CTR S/PANEL BRKT	0.00	0.00	*15.00 F ?
85	1		*L/F DEFORMATION ELEM	0.00	0.00	*55.00 F ?
86	1		*L/F GRILLE	0.00	0.00	*135.00 F ?
87	1		*L/F INNER SUPPORT	0.00	0.00	*170.00 F ✓
88	1		*L/F LIP	0.00	0.00	*230.00 F ?
89	1		*L/F LWR DAMPER	0.00	0.00	*90.00 F ?
90	1		*L/F LWR DEFORM ELEM	0.00	0.00	*20.00 F ?
91	1		*L/F LWR S/PANEL BRKT	0.00	0.00	*115.00 F ?
92	1		*L/FOG LAMP CARRIER	0.00	0.00	*50.00 F ?
93	1		*L/F PANEL SUPPORT	0.00	0.00	*70.00 F ?
94	1		*L/F SUPPORT MEMBER	0.00	0.00	*140.00 F ?
95	1		*L/F SUSPN BUFFER	0.00	0.00	*255.00 F ?
96	1		*L/F UPP S/PANEL BRKT	0.00	0.00	*20.00 F ?
97	1		*L/F WASHER JET	0.00	0.00	*30.00 F ?
98	1		*L/F WHEELHOUSE COVER CAP	0.00	0.00	*210.00 F ?
99	1		*L/F WHEELHOUSE COVER	0.00	0.00	*20.00 F ✓
100	1		*L/F W-HOUSE RR COVER	0.00	0.00	*160.00 F ?
101	1		*L/F WING	0.00	0.00	*160.00 F ?
102	1		*L/GAS DISCHARGE LAMP	0.00	0.00	*600.00 F ✓
103	1		*L/LOCK COVER	0.00	0.00	*340.00 F ?
104	1		*L/LWR RADIATOR BRKT	0.00	0.00	*35.00 F ?

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

11/17/22, 2:28 PM

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
105	1		*L/LWR RADIATOR BRKT	0.00	0.00	*40.00 F ?
106	1		*L/LWR RADIATOR HOSE	0.00	0.00	*130.00 F ?
107	1		*L/OIL COOLER HOSE	0.00	0.00	*90.00 F ?
108	1		*L/RADIATOR BRACKET	0.00	0.00	*110.00 F ?
109	1		*L/TORSION CONTROL	0.00	0.00	*15.00 F ?
110	1		*L/UPPER LOCK	0.00	0.00	*40.00 F ?
111	1		*L/UPPER HEADLAMP BRKT	0.00	0.00	*30.00 F ?
112	1		*L/UPPER RADIATOR BRKT	0.00	0.00	*80.00 F ?
113	1		*L/UPPER RADIATOR HOSE	0.00	0.00	*110.00 F ?
114	1		*L/WASHER NOZZEL TRIM	0.00	0.00	*60.00 F ?
115	1		*LEFT HEADLAMP ASSY	0.00	0.00	*2,640.00 F ?
116	1		*L LED-MODUL SET	0.00	0.00	*290.00 F ?
117	1		*LOW TONE HORN	0.00	0.00	*130.00 F ?
118	1		*LWR EXPANS TANK HOSE	0.00	0.00	*90.00 F ?
119	1		*OUTLET HEATER HOSE	0.00	0.00	*70.00 F ?
120	1		*R/AIR COOLER HOSE	0.00	0.00	*420.00 F ?
121	1		*R/AIR INTAKE TRIM	0.00	0.00	*100.00 F ?
122	1		*R/BONNET HINGE	0.00	0.00	*105.00 F ?
123	1		*R/BONNET LOCK	0.00	0.00	*110.00 F ?

F=Franchise part.

Sub Total (\$\$)

27,825.00

+ Margin on L,N Items 10.00% (\$\$)

2,782.50

Total Parts (\$\$)

30,607.50

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

11/17/22, 2:28 PM

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	AIRCON GAS
2	1	FRONT BUMPER RIVET & CLIPS
3	1	RADIATOR COOLANT

60.00
100.00
30.00

Sub Total (\$\$) 190.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	LABOUR FOR SPRAY PAINTING
---	---------------------------

New 1,200.00

Labour Items

2	LABOUR FOR PANEL BEATING
3	LABOUR TO REMOVE & REFIT AIRCON CONDENSER
4	LABOUR FOR CHECKING WIRING SYSTEM FOR PROPER FUNCTION

New 1,200.00
New 200.00
New 200.00

Gross Labour Cost (\$\$) 2,800.00

Auto Insure Pte Ltd (HQ)/SMF5800P/16/11/2022 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/11/2022 14:22 (SGT)
Reported by	Driver
Date of Accident	11/11/2022 17:15 (SGT)
Exact Location of Accident	KJE, Singapore
Additional Location Information	KJE TURNING INTO CHOA CHU KANG WAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF5800P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	ANDREW KOH
NRIC No	SXXXX386B
Email Address	andrewkoh9533@gmail.com
Mobile Phone No	(Phone) +65-81000040
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	328i
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1997


INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003053801-01

DRIVER

Name of Driver	TAN HUN NEE
NRIC No	SXXXX270C
Date Of Birth	02/04/1981
Occupation	Indoor

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/11/2022 at about 11:50hrs. I was driving KJE turning into choa chu kang way. I assumed that vehicle B will turning out from the slip road as there is no any on coming vehicle but he didn't move, I then collided onto his vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/11/22 11:04hrs

Reporting Centre Person's Signature
Name:
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 386B

Vehicle Details

Vehicle No.: SMF5800P
Vehicle to be Exported: No
Intended Deregistration Date: 14 Nov 2022
Vehicle Make: B.M.W.
Vehicle Model: 328I 2.0 AT D/AB 4DR ABS HID NAV
Primary Colour: Grey
Manufacturing Year: 2012
Engine No.: A3950122N20B20A
Chassis No.: WBA3A52000F253608
Maximum Power Output: 180.0 kW (241 bhp)
Open Market Value: \$44,594.00
Original Registration Date: 29 Mar 2012
First Registration Date: 29 Mar 2012
Transfer Count: 4
Actual ARF Paid: \$44,594.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2031
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$60,586.00
COE Rebate Amount: \$54,299.00
Total Rebate Amount: \$54,299.00

he information contained herein is correct as at 14 Nov 2022

OK