



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA		Ref: CC4/ASM22011510/Upa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 88Y	Veh. Inspected	GBF 1969T
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M04ERX	Excess (\$)	0.00
Assign From		Assign Date	16/11/2022
2. Vehicle Particulars & Condition			
Make & Model	FIAT DOBLO (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZFA26300006C64510	Colour	WHITE
Odometer	186524 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R16	LASSA	6 mm
L/H Front Tyre	195/60 R16	LASSA	6 mm
R/H Rear Tyre	195/60 R16	LASSA	6 mm
L/H Rear Tyre	195/60 R16	LASSA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/11/2022	Inspection Date	16/11/2022
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	