

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

AVON CLEANING SERVICES PTE LTD
33 UBI AVE 3 #04-22 VERTEX
SINGAPORE 408868

Contact : 92989080

TP chin.
Hui Roy

TAX INVOICE

Repair Code : CLM17479

Date in : 15/11/2022

Vehicle Num. : GBM311K

Model : SOKON EC35

Chassis/Eng# : LVPRPB4B2NC893608/-

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Reh d</i>	1	782.00	✓ 782.00
REAR BUMPER REFLECTOR L/R <i>could</i>	2	141.00	✓ 282.00
REAR BUMPER SIDE RETAINER L/R <i>++ could</i>	2	125.00	✓ 250.00
REAR END PANEL (INNER) <i>Dented</i>	1	987.00	<i>545</i> 987.00
REAR END PANEL (OUTER) <i>Dented</i>	1	699.00	✓ 699.00
REAR LH FENDER <i>Buckled</i>	1	1835.00	<i>1280</i> 1,835.00
REAR LH TAILLAMP INNER PANEL <i>Rein</i>	1	489.10	+ 489.10
REAR SPARE TYRE CARRIAGE <i>Bent</i>	1	498.20	<i>325</i> 498.20
REAR SPARE TYRE CARRIAGE SCREW WITH BRACKET <i>Bent</i>	1	98.00	✓ 98.00
REAR TAILGATE <i>Dented</i>	1	1928.00	<i>150</i> 1,928.00
REAR TAILGATE 'LOGO' EMBLEM <i>New</i>	1	73.00	✓ 73.00
REAR TAILGATE CENTER LOCK CONTROL ASSY <i>New</i>	1	569.00	+ 569.00
REAR TAILGATE HINGES L/R <i>New</i>	2	98.00	+ 196.00
REAR TAILGATE INNER TRIM BOARD <i>New</i>	1	400.00	+ 400.00
REAR TAILGATE LOCK STRIKER <i>New</i>	1	79.00	+ 79.00
REAR TAILGATE MECHANISM LOCK <i>New</i>	1	178.00	✓ 178.00
REAR TAILGATE NUMBER PLATE LAMP L/R <i>New</i>	2	105.00	+ 210.00
REAR TAILGATE OUTER HANDLE <i>New</i>	1	325.00	+ 325.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

AVON CLEANING SERVICES PTE LTD
33 UBI AVE 3 #04-22 VERTEX
SINGAPORE 408868

Contact : 92989080

TAX INVOICE

Repair Code : CLM17479

Date in : 15/11/2022

Vehicle Num. : GBM311K

Model : SOKON EC35

Chassis/Eng# : LVPRPB4B2NC893608/-

REAR TAILGATE WEATHER STRIP <i>cut</i>	1	305.00	<i>✓</i>	305.00
REAR TAILLAMP L/R <i>amld</i>	2	469.00	<i>770</i>	938.00
Subtotal before discount				11,121.30
Percentage discount 0%				0.00
Sub-total 1				11,121.30
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER REVERSE SENSOR (3 EYES) - SET <i>new</i>	1	320.00	<i>250</i>	320.00
REAR LH FENDER 3D STICKER <i>new</i>	1	800.00	<i>350</i>	800.00
REAR TAILGATE '70KM' STICKER <i>new</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>+</i>	50.00
REAR TAILGATE NUMBER PLATE <i>new</i>	1	25.00	<i>+</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>not in</i>	1	50.00	<i>+</i>	50.00
REAR TAILGATE OUTER HANDLE CLIPS - SET <i>new</i>	1	40.00	<i>+</i>	40.00
REAR TAILGATE WINDSCREEN SEAL <i>new</i>	1	80.00	<i>40</i>	80.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	<i>40</i>	80.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	25.00	<i>30</i>	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

AVON CLEANING SERVICES PTE LTD
33 UBI AVE 3 #04-22 VERTEX
SINGAPORE 408868

Contact : 92989080

TAX INVOICE

Repair Code : CLM17479
Date in : 15/11/2022
Vehicle Num. : GBM311K
Model : SOKON EC35
Chassis/Eng# : LVPRPB4B2NC893608/-

Subtotal before discount	755	1,600.00
Percentage discount 0%		0.00
Sub-total 2		1,600.00
Parts-total		12,721.30

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total 3,530.00
Parts & Labour Total 16,251.30

50 80.00
120 150.00
50 100.00
1000 800 1,200.00
120 800 1,800.00
60 120.00
80.00

2560

Adrian G
4/5 17/11/22

09. Pungs.

total: 964.30

4/5: 7.61K ✓

*** This is a computer generated document which requires no signature.***

the Repairer of the following: page 3

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: