

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011515/RQP3Q2
Date: 22/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00055032202		
Claimant Vehicle No :	PC8336Z	Insured Vehicle No :	SLB1449E		
Date of Loss:	02/11/2022	Nature of Claim:	TP	Claim No:	SNM22D207920/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8336Z		Engine No:	ISF38E6C16876379296
Make & Model:	GOLDEN DRAGON XML6772J18, 3.8 D (M)		Chassis No:	LL3BDADE8JA011941
Reg. Date:	04/07/2019 (Man. Year: 2018)		Odometer:	198824 km
Colour:	White			
Engine Capacity:	3759 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.50	Rear Tyre Size:	215/75 R17.50 (D)
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7/7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,170.00	945.00	225.00	19.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	500.00	500.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,170.00	1,445.00	725.00	33.41
Approved Total (Overridden) (S\$)		1,150.00		
Nett Amount (S\$)	2,170.00	1,150.00	1,020.00	47.00

INSPECTION

Date of Assignment:	23/11/2022	
Date Inspected:	22/11/2022	Inspected At: One Line Motorworks Trading (HQ) 11 TUAS BAY CLOSE #06-02/06-03 WEST STAR Singapore 636996
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Dec 2022)	
Parts:	N/A	GOLDEN DRAGON XML6772J18 3.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8336Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT LEFT HEADLAMP	Scratched	700.00 FL	*700.00 FL	
2	1		*FRONT LEFT FOG LAMP	Cracked	350.00 FL	*350.00 FL	
3	1		*FRONT LEFT FRONT VIEW MIRROR	Not Necessary	250.00 FL	*- FL	
					Sub Total (\$\$)	1,300.00	1,050.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	130.00	105.00
					Total Parts (\$\$)	1,170.00	945.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /JACK/PANEL BEAT AND SPRAY PAINT MULTI-COLOUR OF ALL AFFECTED ACCIDENTAL PARTS INCLUDING DESIGN PAINTING ON SAME	New	1,000.00	500.00
			Gross Labour Cost (\$)	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >