

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 08 Dec 2022

Preliminary Advice

Insured Vehicle No	: SLB1449E	Accident Date	: 02/11/2022
TP Vehicle No	: PC8336Z	Assignment Date	: 23/11/2022
Make	: GOLDEN DRAGON XML6772J18	Est. Duration of Repair	: 3
Date of Inspection	: 22/11/2022		
Inspection At	: ONE LINE MOTORWORKS TRADING (HQ) 11 TUAS BAY CLOSE #06-02/06-03 WEST STAR SINGAPORE 636996		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,170.00
Revised Amount	:S\$	1,130.00
Check Items (Estimated)	:S\$	385.00
Total	:S\$	1,515.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.