

# One Line Motorworks Trading

11, Tuas Bay Close #06-03  
 West Star, Singapore 636996  
 Tel : 62622106  
 Company Reg No: 53375959E  
 Email : tricia.onelinemotorworks@gmail.com

945  
 500  
 1445  
 20%  
 1156

14 November 2022

China Taiping Insurance (Singapore) Pte Ltd  
 To: Attending Surveyor

BY HAND

L/S - \$1,150 / 3 days

Dear Sirs,

**THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PC8336Z**

**TRAFFIC ACCIDENT ON 02/11/2022 INVOLVING PC8336Z AND SLB1449E NEAR 27 JALAN BESAR AT THE JUNCTION OF JALAN BESAR AND DUNLOP STREET**

We append below our repair estimate for PC8336Z.

Repair Estimate

Parts Required :-

1 Pc	Front Left Headlamp	500	\$	700.00
1 Pc	Front Left Fog Lamp	? Crak	\$	350.00
1 Pc	Front Left Front View Mirror	X nn	\$	250.00 X
		1050	\$	1,300.00
		10%	\$	130.00
	Less 10% trade discount	945	\$	1,170.00

Labour Charges :-

a.	To dismantle/jack/panel beat and spray paint multi-colour of all affected accidental parts including design painting on same	500	\$	1,000.00	500
	Total repair cost		\$	<u>2,170.00</u>	

Note :- This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.

ONE LINE MOTORWORKS TRADING



Neo Say Pheng (H/P : 97971868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Pass  
 Ap 90010068  
 3 days  
 L/S  
 22/11/22 @ 1110  
 Res after repair  
 email: rasul@lkkauto.com