



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM22011522/Kpa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3190Z	Veh. Inspected	GBK 8711Y
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04CM5	Excess (\$)	0.00
Assign From		Assign Date	16/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (A)	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GDH2012015534	Colour	PINK
Odometer	34179 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	BRIDGESTONE	2 mm
L/H Front Tyre	195 R15X8	BRIDGESTONE	2 mm
R/H Rear Tyre	195 R15X8	BRIDGESTONE	2 mm
L/H Rear Tyre	195 R15X8	BRIDGESTONE	2 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/10/2022	Inspection Date	02/12/2022
Survey held at	FORZA AUTOHAUS PTE. LTD. 39 WOODLANDS CLOSE #01-34 MEGA@WOODLANDS SINGAPORE 737856		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	