

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM22011525/Up3

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBE7631H

at Workshop m/s

7 klee

of

Insured:

SHCS208A

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

\$42k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

25

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

B \$69k

Vehicle: IN / OUT

Date:

Person Contacted:

L7A9 12801

Veh No:

GBE7631H

Yr Regn:

22/03/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Car

Make:

Toyota Dyno

c.c 2982

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

22/440

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDY 23/802 3073

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

165 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

6

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

09/11/22

D.O.I.

22/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ref.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Day 136.

2/12/22 check home video  
4/5 \$2800 in hand m/s lee

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

# T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Tklee0247@gmail.com

Vehicle Number: GBE7631H

Vehicle Model: TOYOTA DYNA

MSA Tony  
Not Authorised  
22/11/22  
1/5 \$ 2800  
4 days

| PARTICULAR                |                                                        | AMOUNT      |
|---------------------------|--------------------------------------------------------|-------------|
| QTY                       |                                                        | SS          |
| <u>LIST PRICE</u>         |                                                        |             |
| 1                         | 1 FRONT BUMPER                                         | \$ 748.90   |
| 2                         | 1 FRONT BUMPER FOG LAMP - RH                           | \$ 371.45   |
| 3                         | 1 FRONT BUMPER FOG LAMP COVER                          | \$ 110.25   |
| 4                         | 2 FRONT BUMPER BRACKET - RH / LH @ 314.55              | \$ 683.00   |
| 5                         | 1 FRONT CAB PANEL                                      | \$ 1,291.80 |
| 6                         | 1 FRONT GRILLE                                         | \$ 644.30   |
| 7                         | 1 FRONT GRILLE LOGO                                    | \$ 76.20    |
| 8                         | 2 FRONT HEADLAMP - RH / LH @ 971.34                    | \$ 1,942.68 |
|                           |                                                        | \$ 5,868.58 |
| LESS 25%                  |                                                        | \$ 1,467.15 |
|                           |                                                        | \$ 4,401.44 |
| <u>SPECIAL NETT ITEMS</u> |                                                        |             |
| 1                         | 1 (SET) FRONT BUMPER CLIP                              | \$ 45.00    |
| 2                         | 1 (SET) FRONT NUMBER PLATE                             | \$ 60.00    |
|                           |                                                        | \$ 105.00   |
| <u>LABOUR CHARGES</u>     |                                                        |             |
| 1                         | TO PANEL BEAT,CUT,WELD,REMOVE & REPLACE ACCIDENT PARTS | \$ 600.00   |
| 2                         | TO PUTTY, SPRAY PAINT, & POLISH ACCIDENT PORTION       | \$ 600.00   |
| 3                         | TO CHECK WIRING                                        | \$ 50.00    |
| 4                         | TO CONDUCT COMPUTERISED WHEEL ALIGNMENT                | \$ 50.00    |
|                           |                                                        | \$ 1,300.00 |

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 5,806.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3160-79  
252  
2370.59  
1140  
3510.59  
22  
2808