



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP22011527/Uqy3m4
BLK 1 KAKI BUKIT AVE 6		Date:	01/12/2022
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE			
417883			
ON BEHALF OF SHANGLI BUILDING MATERIAL SUPPLIERS		Code:	TP149
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.		Veh. Inspected	YQ 2107C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HINO XZU605R (M)	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JHHACV3G60K005190	Colour	WHITE / BLUE
Odometer	31404 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/85 R16	BRIDGESTONE	5 mm
L/H Front Tyre	185/85 R16	BRIDGESTONE	5 mm
R/H Rear Tyre	185/85 R16 (D/D)	BRIDGESTONE	5/5 mm
L/H Rear Tyre	185/85 R16 (D/D)	BRIDGESTONE	5/5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & FRONT W/SCREEN CRACKED. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	11/11/2022	Inspection Date	17/11/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	