

ASS. REC. BY:

REF:

AIG-1 22011534/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.3126 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S140 2676 Yr Regn: 11, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 866733 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1ABL15AUC 282311Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: Front 215/60R16R: Railon

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 2/11/22

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/1/22 @ 800h Capu

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD267G

Not Notarized AAD2211-

, 8800

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

14 NOV 2022

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD267G

VF1ABL15AUC282311

200303878K

RENAULT

LATITUDE

02/11/2022

EU8888H/ ATG

20/11/2015

PART

- 1 DOOR PANEL REAR RH
- 1 DOOR WEATHERSTRIP REAR RH
- 1 DOOR HANDLE MODULE REAR RH
- 1 DOOR HANDLE OUTER REAR RH
- 1 DOOR REGULATOR REAR RH
- 1 DOOR REGULATOR MOTOR REAR RH
- 1 DOOR HINGE UPPER REAR RH
- 1 DOOR HINGE LOWER REAR RH
- 1 FENDER PANEL REAR RH
- 1 WHEELARCH REAR RH
- 1 BUMPER COVER REAR
- 1 ROCKER PANEL OUTER RH

LIST

\$	2,844.66
\$	311.60
\$	133.40
\$	42.10
\$	450.60
\$	758.10
\$	241.60
\$	169.90
\$	1,933.20
\$	275.40
\$	561.70
\$	1,184.99

\$ 8,907.25**10% \$ 890.73****\$ 8,016.53****Special Nett**

- 1 FENDER LINER CLIP
- 1 REAR BUMPER CLIP
- 1 RIM
- 1 TYRE
- 1 DOOR TRIM CLIP
- 1 DOOR SEAL CLIP
- 1 DOOR MOULDING CLIP
- 1 DOOR STICKER 65553333
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

\$	60.00	X
\$	60.00	X
\$	350.00	X
\$	300.00	X
\$	70.00	X
\$	65.00	X
\$	70.00	X
\$	100.00	60.00
\$	150.00	X
\$	200.00	X

Trans-cab Auto Services Pte Ltd

AAD2211-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD267G

1 WINDSCREEN INNER SPONGE SEAL

	\$	nn 130.00 X
TOTAL	\$	1,555.00
TOTAL PARTS	\$	9,571.53

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 300/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 440/
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	nn 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To Check Electrical Lighting Concerned.	\$	nn 170.00 X

TOTAL \$ 10,240.00**Over All Total \$ 27,828.05****(LUMP SUM)****Repair Days**20 DAYS
2 days**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD267G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Nov 2022
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002921
Chassis No.:	VF1ABL15AUC282311
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Nov 2015
First Registration Date:	20 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2023
PARF Rebate Amount:	\$12,998.00

Intended COE Rebate Details

COE Expiry Date:	19 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$5,925.00
Total Rebate Amount:	\$18,923.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Nov 2022

OK