



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011536/Tqy3e2 Date: 10/03/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNB 9175T	Veh. Inspected	SMQ 9222Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	DVS22/0127	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	16/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. Z4	c.c	2979	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WBALM12080E393055	Colour	BLACK	
Odometer	137866 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/30 R19	MICHELIN	6 mm	
L/H Front Tyre	265/30 R19	MICHELIN	6 mm	
R/H Rear Tyre	265/30 R19	MICHELIN	6 mm	
L/H Rear Tyre	265/30 R19	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/11/2022	Inspection Date	17/11/2022	
Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619			
5a. Remarks				
A)REGISTRATION DATE: 29 JUN 2010 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	