

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6744 4165 | Fax: (+65) 6744 4604

Reg. No: 201538764H

Email : ca3services@gmail.com

TO : ALLIANZ
ATTENTION : MOTOR CLAIMS DEPT
ESTIMATE REPORT :
DATE : 16/11/2022
JOB TYPE : OD CLAIM

VEHICLE DETAILS

VEHICLE NO : SMZ 9096Z

MODEL : BMW 320I

CHASSIS NO

ACCIDENT DETAILS
DATE : 29-Sep-22
TIME : 17:05HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNITCOST PRICE	TOTAL COST PRICE
1	FRONT SIDE MIRROR <i>Paint</i>	1	\$ 820.00	\$ 820.00
2	FRONT SIDE MIRROR COVER <i>Paint</i>	1	\$ 80.00	\$ 80.00
3	HEADLAMP RH <i>New</i>	1	\$ 1,850.50	\$ 1,850.50
4	FRONT BUMPER <i>Repair</i>	1	\$ 920.50	\$ 920.50
5	FRONT BUMPER SIDE RETAINER RH <i>New</i>	1	\$ 52.00	\$ 52.00
6	FRONT FENDER RH <i>Dented</i>	1	\$ 455.60	\$ 455.60
7	FRONT SHOCK ABSORBER RH <i>3AP</i>	1	\$ 390.00	\$ 390.00
8	FRONT KNUCKLE RH <i>Jan</i>	1	\$ 355.20	\$ 355.20
9	FRONT WHEEL HUP WITH BEARING RH ?	1	\$ 350.00	\$ 350.00
10	1FRONT LOWER ARM (STRAIGHT) ?	1	\$ 310.00	\$ 310.00
11	FRONT LOWER ARM (BENT) ?	1	\$ 322.00	\$ 322.00
12	FRONT DOOR <i>Dented</i>	1	\$ 920.00	\$ 920.00
13	FRONT DOOR LOCK ?	1	\$ 230.50	\$ 230.50
14	FRONT DOOR OUTER HANDLE <i>Dented</i>	1	\$ 155.20	\$ 155.20
15	FRONT DOOR OUTER HANDLE END <i>Crack</i>	1	\$ 90.00	\$ 90.00
16	FRONT DOOR KEYLOCK <i>Paint</i>	1	\$ 180.00	\$ 180.00
17	FRONT DOOR INNER RUBBER <i>New</i>	1	\$ 230.00	\$ 230.00
18	REAR DOOR <i>Dented</i>	1	\$ 920.00	\$ 920.00
19	REAR DOOR LOCK <i>New</i>	1	\$ 255.20	\$ 255.20

20	REAR DOOR OUTER HANDLE <i>at Dehd</i>	1	\$ 155.20	\$ 155.20	✓
21	REAR DOOR OUTER HANDLE END <i>Dehd</i>	1	\$ 90.00	\$ 90.00	✓
22	REAR DOPOR INNER RUBBER <i>new</i>	1	\$ 230.00	\$ 230.00	✓
23	REAR BUMPER <i>Dehd</i>	1	\$ 920.50	\$ 920.50	✓
24	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 55.00	\$ 55.00	✓
25	REAR FENDER <i>Dented</i>	1	\$ 1,255.30	\$ 1,255.30	✓
26	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 55.00	\$ 55.00	✓
27	REAR LOWER ARM RH <i>?</i>	1	\$ 320.00	\$ 320.00	?
28	REAR UPPER ARM RH (FRONT) <i>?</i>	1	\$ 375.00	\$ 375.00	?
29	REAR UPPER ARM RH(REAR) <i>?</i>	1	\$ 435.00	\$ 435.00	?
30	REAR SWING ARM RH <i>?</i>	1	\$ 520.00	\$ 520.00	?
31	REAR KNUCKLE ARM RH <i>gal</i>	1	\$ 411.00	\$ 411.00	+
32	REAR SHOCK ABSORBER RH <i>gal</i>	1	\$ 350.00	\$ 350.00	+
33	REAR WHEEL HUP WITH BEARING RH <i>?</i>	1	\$ 250.50	\$ 250.50	?

TOTAL PRICE \$ 14,309.20

ADD 10% \$ 1,430.92

SUB TOTAL PRICE \$ 15,740.12

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP(SET) <i>new</i>	1	\$ 22.00	\$ 22.00	+
2	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	✓
3	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	60
4	WHEEL TYRE <i>new</i>	2	\$ 380.00	\$ 760.00	+
5	WHEEL RIM <i>gal</i>	1	\$ 1,200.00	\$ 1,200.00	600

TOTAL \$ 2,127.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1300	
3	TUFF COAT	\$ 250.00	80	
4	WIRING CHECK	\$ 180.00	30	
5	TO REMOVE AND REFIX FRONT & REAR DOOR MECHANISM	\$ 280.00	160	

6	TO REMOVE AND REFIX FRONT & REAR UNDERCARRIAGE	\$ 320.00	?	
7	FOUR WHEEL ALIGNMENT	\$ 100.00	80	
8	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 140.00	120	
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 320.00	120	

TOTAL

\$5,190.00

Adrian LG
Not Authorised,
Excess 600
17/11/22 4/5.
10 Days.

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,867.12
TOTAL LABOUR COST : \$ 5,190.00
TOTAL REPAIR COST : \$ 23,057.12

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: