

ASS. REC. BY:

REF:

C72/ 220115381kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

ays

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/12

87575.23

Cable

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S + RS. SI

F. Invs

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF523G*NOT AUTHORIZED
Refurnish B4 paint***AAD2211-063***87575.23*

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 NOV 2022**SHF523G**

200303878K

TOYOTA

PRIUS GEN 4

12/11/2022

SMZ9719K / CHINA TAIPING

16/10/2020

PART**LIST**

- 1 COVER, FRONT BUMPER
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPPER RH
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 UNIT ASSY, HEADLAMP, ~~LH~~ RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO. 1
- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT ~~RH~~ LH
- 1 EMBLEM, SIDE PANEL, ~~RH~~ LH
- 1 LINER, FRONT FENDER, ~~LH~~ RH
- 1 GUIDE, RADIATOR AIR, NO.1 RH
- 1 GUIDE, RADIATOR AIR, NO.1 LH
- 1 HOSE, AIR CLEANER, NO.1
- 1 INLET, AIR CLEANER, NO.2
- 1 CLEANER ASSY, AIR
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 COVER, ENGINE UNDER, NO.1
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2

\$	<i>Tr</i>	521.00	✓
\$	<i>Tr</i>	30.20	✓
\$	<i>Tr</i>	30.20	X
\$	<i>Tr</i>	47.50	X
\$	<i>Tr</i>	59.30	✓
\$	<i>Tr</i>	80.10	X
\$	<i>Tr</i>	100.40	✓
\$	<i>Tr</i>	95.60	✓
\$	<i>Tr</i>	2,637.60	X
\$	<i>Tr</i>	3,772.50	X
\$	<i>Tr</i>	2,637.60	✓
\$	<i>Tr</i>	977.80	✓
\$	<i>Tr</i>	54.60	✓
\$	<i>Tr</i>	210.30	X
\$	<i>Tr</i>	65.30	X
\$	<i>Tr</i>	69.90	X
\$	<i>Tr</i>	74.00	X
\$	<i>Tr</i>	112.70	X
\$	<i>Tr</i>	1,147.00	X
\$	<i>Tr</i>	983.10	✓
\$	<i>Tr</i>	58.90	✓
\$	<i>Tr</i>	58.90	X
\$	<i>Tr</i>	110.50	X
\$	<i>Tr</i>	716.60	✓
\$	<i>Tr</i>	80.20	✓
\$	<i>Tr</i>	472.40	X
\$	<i>Tr</i>	246.10	X
\$	<i>Tr</i>	241.90	X

Trans-cab Auto Services Pte Ltd**AAD2211-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF523G

1	ABSORBER, FRONT BUMPER, LOWER	\$	Sm	132.70	X
1	SUPPORT, RADIATOR, UPPER LH	\$	R	78.90	X
1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	R	377.10	X
1	GRILLE SUB-ASSY, RADIATOR	\$	CM	422.50	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	Dir 1P	178.60	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	R	105.80	X
1	EMBLEM ASSY, MOULDING	\$	Sm	160.50	X
1	MOULDING, WINDSHIELD, OUTSIDE LH	\$	Sm	85.50	X

TOTAL	\$	17,233.80
25%	\$	4,308.45
	\$	12,925.35

Special Nett

1SET BUMPER CLIP FRT	\$	Mr	95.00	60sm
1 FRONT NUMBER PLATE WITH MOULDING	\$	CM	200.00	45sm

TOTAL	\$	295.00
--------------	-----------	---------------

TOTAL PARTS	\$	13,220.35
--------------------	-----------	------------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	500/
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X

Trans-cab Auto Services Pte Ltd**AAD2211-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF523G

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>nn</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>Λ</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	<i>601</i>
Towing Fees	\$	150.00	<i>501</i>
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	<i>6601</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 220.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	<i>X</i>

TOTAL \$ 7,300.00**Over All Total \$ 20,520.35****(PART-BY-PART) Repair Days****10 DAYS**
*3 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF523G**AAD2211-063**

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF523G

200303878K

TOYOTA

PRIUS GEN 4

12/11/2022

SMZ9719K / CHINA TAIPING

16/10/2020

PART**LIST**

- 1 BATTERY
1 LAMP ASSY, FOG, LH

\$ *nd* 1,584.90
\$ *cm* 237.10

509.10
✓

TOTAL	\$	1,822.00
25%	\$	455.50
	\$	1,366.50

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHF523G

Vehicle to be Exported: No

Intended Deregistration Date: 14 Nov 2022

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2020

Engine No.: 2ZR2H01505

Chassis No.: JTDKB3FU403092212

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,807.00

Original Registration Date: 16 Oct 2020

First Registration Date: 16 Oct 2020

Transfer Count: 0

Actual ARF Paid: \$14,530.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Oct 2028

PARF Rebate Amount: \$10,897.00

Intended COE Rebate Details

COE Expiry Date: 15 Oct 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$28,160.00

COE Rebate Amount: \$20,836.00

Total Rebate Amount: \$31,733.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Nov 2022

OK