

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

## Estimated Cost of Repair

|                     |                                            |                                       |
|---------------------|--------------------------------------------|---------------------------------------|
| <b>Attention To</b> | <b>Allianz Insurance Singapore Pte Ltd</b> | <b>Claim Details</b>                  |
|                     | 79 Robinson Road                           | <b>Case Ref. No.</b> : OD/112022/5776 |
|                     | #09-01                                     | <b>Date</b> : 14-11-2022              |
|                     | Singapore 068897                           | <b>Accident Date</b> : 14-11-2022     |

### Vehicle Details

**Make & Model** : Hyundai ELANTRA 1.6 AT ABS D  
**Chassis No** : KMHDH41CMGU655498  
**Registration No** : SKZ9165G

| S/N | Description                                        | Qty   | Amount (\$\$) |   |
|-----|----------------------------------------------------|-------|---------------|---|
| 1   | LH HEADLAMP <i>Scratched</i>                       | 1.00  | \$950.00      | ✓ |
| 2   | LH HEADLAMP LOWER BRACKET <i>HN</i>                | 1.00  | \$30.00       | X |
| 3   | FRONT BUMPER <i>Reache</i>                         | 1.00  | \$240.00      | ✓ |
| 4   | FRONT BUMPER RH FOG LAMP                           | 1.00  | \$150.00      | ? |
| 5   | FRONT BUMPER LH FOG LAMP <i>HN</i>                 | 1.00  | \$150.00      | X |
| 6   | FRONT BUMPER RH FOG LAMP COVER                     | 1.00  | \$20.00       | ? |
| 7   | FRONT BUMPER LH FOG LAMP COVER <i>HN</i>           | 1.00  | \$20.00       | X |
| 8   | FRONT BUMPER RH SIDE RETAINER                      | 1.00  | \$10.00       | ? |
| 9   | FRONT BUMPER LH SIDE RETAINER                      | 1.00  | \$10.00       | ? |
| 10  | FRONT BUMPER RH BRACKET                            | 1.00  | \$30.00       | ? |
| 11  | FRONT BUMPER LH BRACKET                            | 1.00  | \$30.00       | ? |
| 12  | FRONT BUMPER CLIPS <i>Hic</i>                      | 10.00 | \$20.00       | ✓ |
| 13  | FRONT LH FENDER <i>Reache</i>                      | 1.00  | \$240.00      | ✓ |
| 14  | FRONT LH FENDER INNER SHIELD <i>original photo</i> | 1.00  | \$50.00       | ✓ |
| 15  | FRONT LH FENDER INNER SHIELD CLIPS <i>Hic</i>      | 10.00 | \$20.00       | ✓ |
| 16  | FRONT LH FENDER TRIANGLE COVER <i>disbaged HN</i>  | 1.00  | \$20.00       | X |
| 17  | FRONT SPORT RIM (R16") <i>cut</i>                  | 2.00  | \$940.00      | ✓ |
| 18  | FRONT SHOCK ABSORBER                               | 2.00  | \$360.00      | ? |
| 19  | FRONT KNUCKLE ARM                                  | 2.00  | \$400.00      | ? |
| 20  | FRONT KNUCKLE WHEEL BEARING                        | 2.00  | \$140.00      | ? |
| 21  | FRONT LOWER ARM                                    | 2.00  | \$340.00      | ? |
| 22  | FRONT DRIVE SHAFT                                  | 2.00  | \$1,200.00    | ? |
| 23  | FRONT LINK                                         | 2.00  | \$80.00       | ? |
| 24  | ANTI ROLL BAR                                      | 1.00  | \$420.00      | ? |
| 25  | STEERING RACK N PINION                             | 1.00  | \$520.00      | ? |
| 26  | FRONT CROSS MEMBER                                 | 1.00  | \$550.00      | ? |
| 27  | LH SIDE MIRROR ASSY <i>broken</i>                  | 1.00  | \$650.00      | ✓ |
| 28  | LH SIDE MIRROR COVER <i>disbaged</i>               | 1.00  | \$170.00      | ✓ |
| 29  | LH SIDE MIRROR SIGNAL LIGHT <i>disbaged</i>        | 1.00  | \$110.00      | ✓ |
| 30  | LH SIDE MIRROR GLASS <i>disbaged</i>               | 1.00  | \$140.00      | ✓ |

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

|    |                                                        |       |            |   |
|----|--------------------------------------------------------|-------|------------|---|
| 31 | FRONT LH DOOR <i>Knc</i>                               | 1.00  | \$950.00   | ✓ |
| 32 | FRONT LH DOOR OUTER CHROME MOULDING <i>bt</i>          | 1.00  | \$50.00    | ✓ |
| 33 | FRONT LH DOOR PILLAR STICKER <i>Hec</i>                | 1.00  | \$10.00    | ✓ |
| 34 | FRONT LH DOOR OUTER HANDLE - LONG <i>broken</i>        | 1.00  | \$90.00    | ✓ |
| 35 | FRONT LH DOOR OUTER HANDLE - SHORT <i>broken</i>       | 1.00  | \$50.00    | ✓ |
| 36 | FRONT LH DOOR OUTER HANDLE BASE <i>Hec</i>             | 1.00  | \$70.00    | ✓ |
| 37 | FRONT LH DOOR TOP HINGE <i>bt photo</i>                | 1.00  | \$30.00    | ✓ |
| 38 | FRONT LH DOOR LOWER HINGE <i>bt photo</i>              | 1.00  | \$30.00    | ✓ |
| 39 | FRONT LH DOOR CHECK <i>bt photo</i>                    | 1.00  | \$30.00    | ✓ |
| 40 | FRONT LH DOOR STRIKER                                  | 1.00  | \$30.00    | ? |
| 41 | FRONT LH DOOR INNER LOCK <i>Don photo</i>              | 1.00  | \$140.00   | ✓ |
| 42 | FRONT LH DOOR POWER WINDOW MOTOR                       | 1.00  | \$120.00   | ? |
| 43 | FRONT LH DOOR POWER WINDOW GEAR                        | 1.00  | \$150.00   | ? |
| 44 | FRONT LH DOOR INNER TRIMBOARD <i>broken photo</i>      | 1.00  | \$740.00   | ✓ |
| 45 | FRONT LH DOOR RUBBER <i>dyfmed photo</i>               | 1.00  | \$80.00    | ✓ |
| 46 | FRONT LH DOOR GLASS <i>Shattered</i>                   | 1.00  | \$360.00   | ✓ |
| 47 | FRONT LH DOOR GLASS RUN-CHANNEL                        | 1.00  | \$120.00   | ? |
| 48 | FRONT LH DOOR GLASS U-CHANNEL (METAL)                  | 1.00  | \$140.00   | ? |
| 49 | FRONT LH DOOR GLASS INNER CHANNEL                      | 1.00  | \$90.00    | ? |
| 50 | FRONT LH DOOR BODY RUBBER                              | 1.00  | \$80.00    | ? |
| 51 | LH CENTER PILLAR INNER                                 | 1.00  | \$1,200.00 | ? |
| 52 | LH CENTER PILLAR OUTER                                 | 1.00  | \$900.00   | ? |
| 53 | LH ROCKER PANEL <i>Rep</i>                             | 1.00  | \$640.00   | X |
| 54 | REAR LH DOOR <i>Reuhl</i>                              | 1.00  | \$800.00   | ✓ |
| 55 | REAR LH DOOR OUTER MOULDING <i>Sn</i>                  | 1.00  | \$60.00    | X |
| 56 | REAR LH DOOR TOP HINGE <i>bt</i>                       | 1.00  | \$30.00    | ✓ |
| 57 | REAR LH DOOR LOWER HINGE <i>bt</i>                     | 1.00  | \$30.00    | ✓ |
| 58 | REAR LH DOOR CHECK <i>bt</i>                           | 1.00  | \$30.00    | ✓ |
| 59 | REAR LH DOOR POWER WINDOW MOTOR                        | 1.00  | \$90.00    | ? |
| 60 | REAR LH DOOR POWER WINDOW GEAR                         | 1.00  | \$150.00   | ? |
| 61 | REAR LH DOOR TRIMBOARD                                 | 1.00  | \$820.00   | ? |
| 62 | REAR LH DOOR RUBBER                                    | 1.00  | \$80.00    | ? |
| 63 | REAR LH DOOR INNER LOCK                                | 1.00  | \$120.00   | ? |
| 64 | RH TAILLAMP <i>Hec</i>                                 | 1.00  | \$220.00   | X |
| 65 | REAR BUMPER <i>Cut</i>                                 | 1.00  | \$250.00   | ✓ |
| 66 | REAR BUMPER RH SIDE RETAINER                           | 1.00  | \$20.00    | ? |
| 67 | REAR BUMPER CLIPS <i>Hec</i>                           | 10.00 | \$20.00    | ✓ |
| 68 | REAR RH FENDER <i>Deep</i>                             | 1.00  | \$800.00   | ✓ |
| 69 | REAR RH FENDER INNER SHIELD <i>dyfmed / torn photo</i> | 1.00  | \$30.00    | ✓ |
| 70 | REAR RH FENDER INNER SHIELD CLIPS <i>Hec</i>           | 10.00 | \$30.00    | ✓ |
| 71 | REAR RH SPORT RIM (R16") <i>Cut photo</i>              | 1.00  | \$470.00   | ✓ |
| 72 | FRONT LH PILLAR INNER COVER                            | 1.00  | \$80.00    | ? |
| 73 | FRONT LH CUSHION SEAT AIRBAG <i>activated</i>          | 1.00  | \$650.00   | ✓ |
| 74 | LH ROOF AIRBAG <i>activated</i>                        | 1.00  | \$620.00   | ✓ |

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

|    |                                                    |      |                     |          |
|----|----------------------------------------------------|------|---------------------|----------|
| 75 | ROOFLINING <i>changed</i>                          | 1.00 | \$850.00            | ✓        |
| 76 | AIRBAG ECU <i>changed</i>                          | 1.00 | \$800.00            | ✓        |
| 77 | AIRBAG SENSOR <i>changed</i>                       | 1.00 | \$70.00             | ✓        |
| 78 | FRONT LH CUSHION SEAT METAL FRAME <i>thin torn</i> | 1.00 | LR 600/- \$1,400.00 | LR 500/- |
| 79 | LH SEAT BELT PILLAR TOP COVER                      | 1.00 | \$210.00            | ?        |
| 80 | LH SEAT BELT PILLAR LOWER COVER                    | 1.00 | \$160.00            | ?        |
| 81 | REAR LH PILLAR COVER <i>thin</i>                   | 1.00 | \$100.00            | X        |

Margin: 10%

\$23,100.00  
\$2,310.00

|    |                                                 |      |            |        |
|----|-------------------------------------------------|------|------------|--------|
| 82 | FRONT TYRE (205/55R16) <i>thin</i>              | 2.00 | \$560.00   | X      |
| 83 | REAR RH TYRE (205/55R16) <i>thin</i>            | 1.00 | \$280.00   | X      |
| 84 | TO CHECK WHEEL ALIGNMENT                        | 1.00 | \$150.00   | 60/-   |
| 85 | TO RESET HEADLAMP SYSTEM                        | 1.00 | \$280.00   | thin   |
| 86 | TO REMOVE AND REFIX FRONT UNDERCARRIAGE         | 1.00 | \$380.00   | 250/-  |
| 87 | TO REMOVE AND REFIX SEAT CUSHION AND ROOFLINING | 1.00 | \$500.00   | 120/-  |
| 88 | TO RESET AIRBAG SYSTEM                          | 1.00 | \$580.00   | 180/-  |
| 89 | TO REPAIR DAMAGES                               | 1.00 | \$2,200.00 | 1800/- |
| 90 | TO SPRAY PAINTING                               | 1.00 | \$2,400.00 | 1800/- |

Subtotal w/o GST:

\$32,740.00

17/11/2022 @ 153m

Not Audited

H/cmr

*[Signature]*

Excess TBA.

2K1c Aud

*[Signature]*

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: