Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Ltd.

79 Robinson Road #09-01

Singapore 068897

Allianz Insurance Singapore Pte. From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn: JANICE KOH Date: 24 Nov 2022

Preliminary Advice

Vehicle No : SKZ9165G Accident Date : 14/11/2022

: HYUNDAI ELANTRA Make Policy No.

SP2000757249-

01

Assignment : 17/11/2022

Date

: S\$600.00

Date of : 17/11/2022

Inspection

Repair

Est. Duration of

Excess

: 14

Inspection At: VIN'S MOTOR PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 32,740.00 Revised Amount :S\$ 25,842.00 Check Items (Estimated) :S\$ 0.00 :S\$ 25,842.00 Total

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 49,000.00 COE / PARF Rebate :S\$ 24,976.00

:S\$ Salvage Value

:S\$ 24,024.00 Margin for Repair

Remarks

(X)	The vehicle is rep	pairable at our ad	ljusted amount	t. We have also	confirmed
	excess and policy coverage. Kindly let us have your authorisation				

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : KINDLY APPROVE ON CHECK ITEMS.

The Repairer agreed to repair the vehicle not more than \$24,000.00