

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01
 SGX Centre 2
 Singapore 068807
 Hot line : 6827 - 7660
 Fax : 6225- 7402 (CLAIM)

Veron

Quotation

DATE : 05.12.2022
 VEH NO : SLE499B
 MODEL : Honda Vezel
 D O A : 15.11.2022
 YR REF : SLF8287M

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLE499B (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO LIST ITEMS</u>			
1	Rear Bumper <i>Reband</i>	1	765.40 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	49.00 ✓
3	Rear Bumper Reflector - LH & RH <i>new new</i>	2	282.20 ✕
4	Rear End Panel <i>new new</i>	1	585.40 ✕
5	Rear End Panel Top Garnish <i>new</i>	1	98.40 ✕
6	Rear End Panel Buzzer <i>new new</i>	1	85.20 ✕
7	Rear End Panel Antenna Sensor <i>new new</i>	1	101.40 ✕
8	Tailgate <i>Dented</i>	1	1,100.00 ✓
9	Tailgate Lock <i>Dented</i>	1	182.50 ✓
10	Tailgate Weatherstripe <i>new</i>	1	194.90 ✕
11	Tailgate Glass Moulding <i>new</i>	1	120.40 ✓
12	Vezel Emblem <i>new</i>	1	45.90 ✓
13	Spare Tyre Panel Undercover <i>new new</i>	1	285.10 ✕
14	Rear Exhaust Pipe <i>Repair</i>	1	598.60 ✕
15	Rear Exhaust Pipe Mounting <i>new new</i>	1	35.40 ✕
16	Rear Exhaust Pipe Gasket <i>new new</i>	1	33.40 ✕
			\$ 4,563.20
	Less 20%		(912.64)
			\$ 3,650.56

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
2	Rear Bumper Outer Chrome Moulding <i>Best</i>	1	250.00 <i>180</i>
3	Rear Bumper Top Garnish <i>Best</i>	1	350.00 <i>250</i>
4	Reverse Sensor <i>Dented</i>	1 set	280.00 <i>200</i>
5	Rear End Panel Top Garnish Clips <i>new new</i>	1 set	20.00 ✕

RE : ESTIMATE FOR ACCIDENT REPAIR SLE499B (HONDA VEZEL)

6	Rear End Panel Sealant <i>NEC</i>	1	720	60.00	*
7	Tailgate Glass Sealant <i>NEC</i>	1		60.00	/
8	Spare Tyre Panel Undercover Clips <i>NEC</i>	1 set		30.00	x.
Total parts				<u>\$ 4,730.56</u>	

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts			\$ 1,200.00	500
2	To putty & spray up paint works			\$ 1,000.00	400
3	To check wiring			\$ 100.00	30
4	To remove reverse sensor			\$ 100.00	50
5	To remove rear camera	<i>1390</i>		\$ 100.00	50
6	To remove rear video recorder			\$ 100.00	50
7	To remove upholstery			\$ 150.00	30
8	To transfer tailgate fittings			\$ 150.00	80
9	To remove tailgate glass			\$ 180.00	120
10	To remove rear exhaust pipe			\$ 150.00	80
Total Labour				\$ 3,230.00	
GRAND TOTAL				\$ 7,960.56	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*total: 3920.56
H/s: 3.1K.
04 Days.*