



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011551/Rny3e2 Date: 15/12/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 346M	Veh. Inspected	SBS 3361P	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/11/22/5028	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	17/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLVO B9TL	c.c	9364	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	YV3S4P921DA161369	Colour	GREEN	
Odometer	544829 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/11/2022	Inspection Date	17/11/2022	
Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	