

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01013/2022/EQ
DATE : 16-Nov-22
WIP : 50726

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ANKIT SHARMA
ADDRESS : 53 TAMPINES AVE 1
#02-04
SINGAPORE 529772
TELEPHONE : HP +65 91470399
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100443365-06
VEHICLE NO : SKX 5735 Z
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TF
MODEL YEAR : 18/12/2015
ENGINE NO : CZC 288938
CHASSIS NO : WAUZZZ8V1GA044303
MILEAGE : 100,670
DATE IN : 15-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Nov-22
PLACE OF ACCIDENT : DRIVING ALONG BEACH ROAD BEFORE
ALJUNIED STREET

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKX 5735 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	Xnn
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250 ✓
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	? Xnn
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	/
5	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,800.00	? /
TOTAL LABOUR CHARGES		:	\$ 5,590.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKX 5735 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS SILL PANEL. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	1500 ✓
7 X	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS ROOF CHANNEL, LHS SILL PANEL AND DOOR ENTRANCE.	\$ 5,500.00	2200 ✓
8	TO INSTALL SOLAR FILM ON LHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	X n ✓
9	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 16,894.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5735 Z

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de/</i>	1	\$ 2,146.00	<i>1116.80</i>
2	FRONT BUMPER FIXING PARTS <i>? Xnn</i>	1	\$ 195.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>? Xnn</i>	1	\$ 175.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH <i>? Xnn</i>	1	\$ 122.00	
5	FRONT BUMPER GUIDE SECTION - LH <i>cm/</i>	1	\$ 71.00	<i>56.48</i>
6	FRONT FENDER - LH <i>bt/</i>	1	\$ 954.00	<i>763.20</i>
7	FRONT FENDER ATTACHMENT PARTS <i>? Xnn</i>	1	\$ 75.00	
8	FRONT FENDER BRACKET - LH <i>ne/</i>	1	\$ 44.40	<i>56.00</i> <i>44.00</i>
9	FRONT FENDER RIVET <i>ne/</i>	8	\$ 31.00	<i>24.32</i>
10	FRONT FENDER CLOSING ELEMENT <i>? bt/</i>	1	\$ 68.00	<i>54.24</i>
11	FRONT FENDER BRACE <i>? bt/</i>	1	\$ 107.00	<i>85.60</i>
12	FRONT FENDER BRACKET - LH <i>? Xnn</i>	1	\$ 31.00	
13	FRONT FENDER CLOSING ELEMENT - LH <i>? Xnn</i>	1	\$ 37.00	
14	FRONT WHEEL HOUSING LINER - LH <i>de/</i>	1	\$ 183.00	<i>146.40</i>
15	HEADLIGHT GAS DISCHARGE LAMP - LH <i>cm/</i>	1	\$ 2,810.00	<i>2248.00</i>
16	LIFT CYLINDER - LH <i>? Xnn</i>	1	\$ 211.00	
17	LIFT CYLINDER HOSE <i>? Xnn</i>	1	\$ 204.00	
18	FRONT EXTERIOR WING MIRROR MOUNTING - LH <i>cm/</i>	1	\$ 1,130.00	<i>904.00</i>
19	FRONT WING MIRROR CAP - LH <i>mlo/</i>	1	\$ 180.00	<i>143.60</i>
20	FRONT WING MIRROR GLASS - LH <i>Xnn</i>	1	\$ 239.00	
SUB TOTAL SPARE PARTS		:	\$ 9,025.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5735 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT WINDOW CORNER TRIM - LH <i>sc</i>	1	\$ 51.00	<i>40.40</i>	
22	FRONT WINDOW GUIDE - LH <i>sc</i>	1	\$ 467.00	<i>373.60</i>	
23	FRONT WINDOW SLOT SEAL TRIM STRIP - LH <i>sc</i>	1	\$ 302.00	<i>241.20</i>	
24	FRONT WINDOW CHROME ROOF MOLDING - LH <i>sc</i>	1	\$ 665.00	<i>531.60</i>	
25	FRONT WINDOW WATER DEFLECTOR STRIP - LH <i>Xnn</i>	1	\$ 75.00		
26	FRONT DOOR WINDOW - LH <i>Xnn</i>	1	\$ 257.00		
27	FRONT SIDE PANEL - LH <i>requir</i>	1	\$ 3,734.00		
28	FRONT WINDOW SILL TRIM STRIP <i>Xnn</i>	1	\$ 140.00		
29	FRONT WINDOW STONE CHIP GUARD - LH <i>?Xnn</i>	1	\$ 82.00		
30	ADHESIVE TAPE <i>?Xnn</i>	1	\$ 59.00		
31	AIRBAG / CHILD'S SEAT STICKER <i>?Xnn</i>	1	\$ 27.00		
32	FRONT ALUMINIUM RIM <i>sc</i>	1	\$ 1,303.00	<i>1042.40</i>	
33	FRONT ALUMINIUM RIM RUBBER VALVE <i>sc</i>	1	\$ 4.00	<i>2.96</i>	
34	FRONT ASSEMBLY CARRIER <i>?bt</i>	1	\$ 1,108.00	<i>886.40</i>	
35	BONDED RUBBER BUSHES - UPPER / LOWER <i>?bt</i>	1	\$ 179.00	<i>142.80</i>	
36	LOWER CONTROL ARM - LH <i>?bt</i>	1	\$ 394.00	<i>314.80</i>	
37	STABILIZER <i>?Xnn</i>	1	\$ 452.00		
38	FRONT WHEEL BEARING HOUSING <i>?bt</i>	1	\$ 628.00	<i>502.40</i>	
39	FRONT WHEELHUB BEARING <i>?bt</i>	1	\$ 554.00	<i>443.20</i>	
40	GUIDE JOINT <i>?bt</i>	1	\$ 137.00	<i>109.60</i>	
SUB TOTAL SPARE PARTS		:	\$ 10,618.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5735 Z

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	COUPLING ROD ? <i>Xan</i>	1	\$ 105.00	
42	GAS SHOCK ABSORBER ? <i>Xan</i>	1	\$ 282.00	
43	DRIVE SHAFT - LH ? <i>Xan</i>	1	\$ 1,521.00	
44	FRONT STEERING GEAR ? <i>Xan</i>	1	\$ 5,552.00	
45	TRACK ROD ? <i>ht</i>	1	\$ 99.00	<i>78.56</i>
46	TIE ROD END - LH ? <i>ht</i>	1	\$ 126.00	<i>100.40</i>
47	ACRYLIC SEALANT ? <i>Xan</i>	S/N	\$ 180.00	
48	CAVITY WAX ? <i>Xan</i>	S/N	\$ 140.00	
49	STONE CHIP ? <i>new</i>	S/N	\$ 180.00	<i>/</i>
50	METAL FILLER POWDER ? <i>Xan</i>	S/N	\$ 280.00	
51	SUNDRIES ? <i>new</i>		\$ 800.00	<i>238.64</i>
TOTAL SPARE PARTS		:	\$ 28,908.00	
TOTAL LABOUR CHARGES		:	\$ 16,894.00	
GRAND TOTAL		:	\$ 45,802.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Resue - 4p 90010068
16/11/22 @ 1545
6 days + 3 = 9 days
p/p

EXCESS: TBA

Rentor / Resue before paint

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/01013/2022/EQ 21-Nov-22 CHANG 1 of 1 SKX 5735 Z AUDI A3 SPORTBACK 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO RENEW RHS FRONT RIM. S/N	\$ 40.00	
2	TO REPAIR LHS SILL PANEL.	\$ 700.00 250	
Parts			
1	WASH WATER RESERVOIR <i>de</i>	\$ 226.00	180.40
2	FRONT RIM - RHS <i>sa</i>	\$ 1,303.00	1042.40
GRAND TOTAL		\$ 2,269.00	

For Premium Automobiles Pte Ltd



Authorised Signature

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/01013/2022/EQ 29-Nov-22 CHANG 1 of 1 SKX 5735 Z AUDI A3 SPORTBACK 1.4 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	REAR 1/4 GLASS CHROME TRIM - LH <i>see</i>	\$ 293.00	234.00
2	HEADLIGHT POWER MODULE <i>faulty</i>	\$ 635.00	507.60
GRAND TOTAL		\$ 928.00	

For Premium Automobiles Pte Ltd

29/11 - by Rasul


Authorised Signature