


PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/01013/2022/EQ 21-Nov-22 CHANG 1 of 1 SKX 5735 Z AUDI A3 SPORTBACK 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO RENEW RHS FRONT RIM. S/N	\$ 40.00	
2	TO REPAIR LHS SILL PANEL.	\$ 700.00 250	
Parts			
1	WASH WATER RESERVOIR <i>de</i>	\$ 226.00	
2	FRONT RIM - RHS <i>sa</i>	\$ 1,303.00	
GRAND TOTAL		\$ 2,269.00	

For Premium Automobiles Pte Ltd



Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKX 5735 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	?
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	/
5	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,800.00	? /
TOTAL LABOUR CHARGES		: \$ 5,590.00	

+ 3 working days ✓
Renu Fel