

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01013/2022/EQ
DATE : 16-Nov-22
WIP : 50726

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Rasul
9 days exclude 1 S
20 Mar 23 Johnny*

OWNER'S NAME : MR ANKIT SHARMA
ADDRESS : 53 TAMPINES AVE 1
#02-04
SINGAPORE 529772
TELEPHONE : HP +65 91470399
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100443365-06
VEHICLE NO : **SKX 5735 Z**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TF
MODEL YEAR : 18/12/2015
ENGINE NO : CZC 288938
CHASSIS NO : WAUZZZ8V1GA044303
MILEAGE : 100,670
DATE IN : 15-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Nov-22
PLACE OF ACCIDENT : DRIVING ALONG BEACH ROAD BEFORE
ALJUNIED STREET

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKX 5735 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
5	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,800.00	\$ 2,800.00
TOTAL LABOUR CHARGES		:	\$ 5,590.00	\$ 3,330.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKX 5735 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 3,330.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS SILL PANEL. TO REPAIR LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,500.00	\$ 1,500.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS ROOF CHANNEL, LHS SILL PANEL AND DOOR ENTRANCE.	\$	5,500.00	\$ 2,200.00
8	TO INSTALL SOLAR FILM ON LHS FRONT DOOR WINDOW GLASS.	S/N \$	400.00	
9	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 520.00
10	ADD LABOUR	\$	740.00	\$ 290.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 17,634.00	\$ 8,224.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5735 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,146.00	\$	1,716.80
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00		
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 175.00		
4	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 122.00		
5	FRONT BUMPER GUIDE SECTION - LH	1	\$ 71.00	\$	56.48
6	FRONT FENDER - LH	1	\$ 954.00	\$	763.20
7	FRONT FENDER ATTACHMENT PARTS	1	\$ 75.00		
8	FRONT FENDER BRACKET - LH	1	\$ 56.00	\$	44.40
9	FRONT FENDER RIVET	8	\$ 31.00	\$	24.32
10	FRONT FENDER CLOSING ELEMENT	1	\$ 68.00	\$	54.24
11	FRONT FENDER BRACE	1	\$ 107.00	\$	85.60
12	FRONT FENDER BRACKET - LH	1	\$ 31.00		
13	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00		
14	FRONT WHEEL HOUSING LINER - LH	1	\$ 183.00	\$	146.40
15	HEADLIGHT GAS DISCHARGE LAMP - LH	1	\$ 2,810.00	\$	2,248.00
16	LIFT CYLINDER - LH	1	\$ 211.00		
17	LIFT CYLINDER HOSE	1	\$ 204.00		
18	FRONT EXTERIOR WING MIRROR MOUNTING - LH	1	\$ 1,130.00	\$	904.00
19	FRONT WING MIRROR CAP - LH	1	\$ 180.00	\$	143.60
20	FRONT WING MIRROR GLASS - LH	1	\$ 239.00		
SUB TOTAL SPARE PARTS		:	\$ 9,025.00	\$	6,187.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5735 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	6,187.04
21	FRONT WINDOW CORNER TRIM - LH	1	\$ 51.00	\$	40.40
22	FRONT WINDOW GUIDE - LH	1	\$ 467.00	\$	373.60
23	FRONT WINDOW SLOT SEAL TRIM STRIP - LH	1	\$ 302.00	\$	241.20
24	FRONT WINDOW CHROME ROOF MOLDING - LH	1	\$ 665.00	\$	531.60
25	FRONT WINDOW WATER DEFLECTOR STRIP -LH	1	\$ 75.00		
26	FRONT DOOR WINDOW - LH	1	\$ 257.00		
27	FRONT SIDE PANEL - LH	1	\$ 3,734.00		
28	FRONT WINDOW SILL TRIM STRIP	1	\$ 140.00		
29	FRONT WINDOW STONE CHIP GUARD - LH	1	\$ 82.00		
30	ADHESIVE TAPE	1	\$ 59.00		
31	AIRBAG / CHILD'S SEAT STICKER	1	\$ 27.00		
32	FRONT ALUMINIUM RIM	1	\$ 1,303.00	\$	1,042.40
33	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	\$	2.96
34	FRONT ASSEMBLY CARRIER	1	\$ 1,108.00	\$	886.40
35	BONDED RUBBER BUSHES - UPPER / LOWER	1	\$ 179.00	\$	142.80
36	LOWER CONTROL ARM - LH	1	\$ 394.00	\$	314.80
37	STABILIZER	1	\$ 452.00		
38	FRONT WHEEL BEARING HOUSING	1	\$ 628.00	\$	502.40
39	FRONT WHEELHUB BEARING	1	\$ 554.00	\$	443.20
40	GUIDE JOINT	1	\$ 137.00	\$	109.60
SUB TOTAL SPARE PARTS			:	\$ 10,618.00	\$ 10,818.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 5735 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 10,818.40</i>
41	COUPLING ROD	1	\$ 105.00	
42	GAS SHOCK ABSORBER	1	\$ 282.00	
43	DRIVE SHAFT - LH	1	\$ 1,521.00	
44	FRONT STEERING GEAR	1	\$ 5,552.00	
45	TRACK ROD	1	\$ 99.00	<i>\$ 78.56</i>
46	TIE ROD END - LH	1	\$ 126.00	<i>\$ 100.40</i>
47	ACRYLIC SEALANT	S/N	\$ 180.00	
48	CAVITY WAX	S/N	\$ 140.00	
49	STONE CHIP	S/N	\$ 180.00	<i>\$ 180.00</i>
50	METAL FILLER POWDER	S/N	\$ 280.00	
51	ADD PARTS		\$ 928.00	\$ 741.60
52	ADD PARTS		\$ 1,529.00	\$ 1,222.80
53	SUNDRIES		\$ 800.00	<i>\$ 238.64</i>
TOTAL SPARE PARTS		:	\$ 31,365.00	\$ 13,380.40
TOTAL LABOUR CHARGES		:	\$ 17,634.00	\$ 8,224.00
GRAND TOTAL		:	\$ 48,999.00	\$ 21,604.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-14/02/23



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/01013/2022/EQ 21-Nov-22 CHANG 1 of 1 SKX 5735 Z AUDI A3 SPORTBACK 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO RENEW RHS FRONT RIM.	S/N	\$ 40.00	\$ 40.00
2	TO REPAIR LHS SILL PANEL.		\$ 700.00	\$ 250.00
			\$ 740.00	\$ 290.00
<u>Parts</u>				
1	WASH WATER RESERVOIR	1	\$ 226.00	\$ 180.40
2	FRONT RIM - RHS	1	\$ 1,303.00	\$ 1,042.40
		PARTS	\$ 1,529.00	\$ 1,222.80
		LABOUR	\$ 740.00	\$ 290.00
GRAND TOTAL			\$ 2,269.00	\$ 1,512.80

For Premium Automobiles Pte Ltd

 Authorised Signature



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/01013/2022/EQ 29-Nov-22 CHANG 1 of 1 SKX 5735 Z AUDI A3 SPORTBACK 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	REAR 1/4 GLASS CHROME TRIM - LH	1	\$ 293.00	\$ 234.00
2	HEADLIGHT POWER MODULE	1	\$ 635.00	\$ 507.60
GRAND TOTAL			\$ 928.00	\$ 741.60

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT