

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921
 Email: ryderautoworkshop@gmail.com
 Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLU9753Z

Model:

Accident Date : 15/11/22

3P:

Location : SLE CITY EXIT OF WOODLANDS AVE 2

7P Budget Direct. Kin Yu.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

19/12/2017

Acknowledged by Repairer
 Signature: (GENERAL)
 Date:

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Red</i>	681.40		
2	10pcs	Rear bumper clips <i>u</i>		40.00	30.
3	2pcs	Rear bumper screw clips <i>new</i>		20.00	t.
4	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	162.20	x.	
5	2pcs	Rear reverse sensor <i>Demod</i>		380.00	2w
6	1pc	Rear end panel <i>new</i>	881.90	+	
7	1pc	Rear end panel inner trim	453.50	+	
8	8pcs	Rear end panel inner trim clips <i>green</i>		32.00	x
9	1pc	Rear o/s tail lamp	678.20	+	
10	1pc	Rear o/s tail lamp panel <i>part</i>	165.10	+	
11	2pcs	Rear Regn. No. Plate lamp	167.50	+	
12	1pc	Rear boot cover <i>Painted</i>	1,174.40	✓	
13	1pc	Rear boot cover weatherstrip <i>new</i>	274.40	+	
14	1pc	Rear boot cover emblem	61.50	✓	
15	1pc	Rear boot cover 'Toyota' emblem <i>part</i>	61.70	-	
16	1pc	Rear boot cover 'PriusC' emblem	67.70	-	
17	1pc	Rear boot cover 'Hybrid' emblem	67.70	-	
18	1pc	Rear boot cover inner trim <i>new</i>	582.25	+	
19	11pcs	Rear boot cover inner trim clips <i>new</i>		44.00	+
20	1pc	Rear boot cover moulding chrome <i>yellow</i>	385.50	+	
21	4pcs	Rear boot cover moulding chrome clips		16.00	+
22	1pc	Rear boot cover lock (Upper) <i>new</i>	291.60	✓	
23	1pc	Rear boot cover lock (Lower) <i>new</i>	43.10	+	
24	1pc	Rear n/s fender wheel guard	263.80	+	
25	6 pcs	Rear o/s & n/s fender wheel guard clips <i>new</i>		24.00	+
26	1pc	Rear o/s fender inner trim	823.20	+	
27	8pcs	Rear o/s & n/s fender inner trim clips <i>new</i>		24.00	+
28	1 pc	Rear windscreen sealant		80.00	60
29	1 pc	Rear windscreen moulding <i>new</i>		120.00	✓
30	1 pc	Rear regn. no. plate <i>part</i>		45.00	+
31	1 pc	Rear regn. no. plate bracket <i>part</i>		29.00	+
Sub Total:			7,286.65	854.00	0.00
			25%	0%	0%
After Less %:			5,464.99	854.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.		1,400.00	400
2		To spray painting.		1,200.00	400
3		To remove & refit rear windscreen		140.00	120
4		To remove and refit rear upholstery to facilitate repair		100.00	40
5		To remove & replace rear reverse sensor camera.		50.00	✓
6		To remove and replace rear tail gate <i>fitting</i>		120	60
7		To re set electrical system. <i>new</i>		280.00	x.
8		To check wiring.		100.00	30
9		To re seal anti rust.		100.00	40
Sub Total:				3,490.00	
Total:				9,808.99	
After Less 20%:				7,847.19	

2406
 1804.50
 S.N: 434.

Adrian G
 2/2 23/11/22.
 04 Days.
 1140

total: 3378.50
 w/s: 2.71c ✓

Chan San Choon
 Chan San Choon
 Director
 DipEng, AAE MIMI,MSAE(Aust)

