



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI22011584/Gny3q2

Date: 16/12/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SG 5058P	Veh. Inspected	SMB 51M
Policy No.	D-19094111MFB	Coverage (\$)	0.00
Claim No.	D22003624MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	17/11/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ OC500LE1830H	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WEB63442021000123	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2022	Inspection Date	18/11/2022
Survey held at	310 MANDAI RD S 779404		
Repairer	TOWER TRANSIT SINGAPORE PTE. LTD.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------