

## Vehicle Damage Assessment Report for [SG5794Y]

Estimate Created: 14/02/2023 02:49 by Insurlogic 1 (Insurlogic\_Pte\_Ltd)

Owned: 14/02/2023 02:52 by Insurlogic 1 (Insurlogic\_Pte\_Ltd)

### General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

### Vehicle Information

Brand	Toyota	Model	Proace
Engine Type			
License Plate Number	SG5794Y	VIN (or Chassis #)	

### Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

### Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$3768.00 with 4 days for repair

Insurlogic 1 (14/02/2023 02:52)

**Parts**

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
NS REAR LAMP COVER		1	800.00	-10.00 %	720.00
REAR LAMP STOP ASSY LED		1	220.00	-10.00 %	198.00
REAR SIGNAL LAMP ASSY LED		1	300.00	-10.00 %	270.00

Parts Subtotal 1,188.00

**Labor****Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	1300.00	0.00 %	1,300.00

**Paint**

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	1280.00	0.00 %	1,280.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,300.00

Paint Labor Subtotal 1,280.00

Labor Subtotal 2,580.00

**Summary**

Repair Cost 3,768.00

Discount(0 %) (0.00)

3,768.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 3,768.00