

# SIN FATT DIESEL MOTOR

BLOCK 3020A UBI ROAD 1 #01-33 SINGAPORE 408714

16<sup>th</sup> NOV 2022

BLOCK 3020A UBI ROAD 1  
# 01-33  
Singapore 408714

TP Allianz  
Xiao Tony

Accident date: 13<sup>rd</sup> NOV 2022

Estimated repair cost for vehicle no: SML496K KIA CERATO 1.6A 2019

| S/n | Qty | Items                                          | U/price  | Amount   |     |
|-----|-----|------------------------------------------------|----------|----------|-----|
| 1   | 1   | Front bonnet <i>Deformed</i>                   |          | \$952.10 | ✓   |
| 2   | 1   | Front bonnet lock <i>new</i>                   |          | \$112.00 | x   |
| 3   | 1   | front grille <i>new</i>                        |          | \$325.10 | x   |
| 4   | 1   | front grille emble logo <i>new</i>             |          | \$65.00  | x   |
| 5   | 8   | Front grille clips                             | \$6.50   | \$52.00  | ✓   |
| 6   | 1   | front support panel <i>Deformed</i>            |          | \$785.20 | ✓   |
| 7   | 1   | Front headlamp-RH <i>Cracked</i>               |          | \$852.10 | ✓   |
| 8   | 2   | Front headlamp lower bracket <i>new</i>        | \$135.20 | \$270.40 | x   |
| 9   | 1   | Front bumper <i>Distorted</i>                  |          | \$785.20 | 640 |
| 10  | 1   | Front Bumper Side Bracket <i>new</i>           |          | \$35.80  | ✓   |
| 11  | 10  | Front bumper clips <i>new</i>                  | \$6.50   | \$65.00  | 30  |
| 12  | 1   | Front bumper fog lamp-RH <i>missing</i>        |          | \$185.20 | ✓   |
| 13  | 1   | Front bumper fog lamp cover <i>new</i>         |          | \$85.20  | ✓   |
| 14  | 1   | Front bumper lower grille <i>new</i>           |          | \$285.20 | ✓   |
| 15  | 1   | Front Bumper towing cover <i>new</i>           |          | \$75.00  | 28  |
| 16  | 1   | front lower bumper <i>new</i>                  |          | \$388.20 | x   |
| 17  | 1   | front Bumper Lower Beam <i>new</i>             |          | \$211.00 | 155 |
| 18  | 1   | front signal lamp -RH <i>new</i>               |          | \$95.20  | ✓   |
| 19  | 1   | Front signal lamp cover -RH <i>new</i>         |          | \$85.20  | ✓   |
| 20  | 2   | Front bumper side retainer <i>new</i>          | \$185.20 | \$370.40 | x   |
| 21  | 1   | Front bumper reinforcement <i>new</i>          |          | \$488.20 | ✓   |
| 22  | 1   | Front bumper inner sponge <i>new</i>           |          | \$185.20 | ✓   |
| 23  | 1   | front bumper side air cover -RH <i>new</i>     |          | \$155.20 | 45  |
| 24  | 1   | Water tank assy <i>Deformed</i>                |          | \$255.30 | 125 |
| 25  | 1   | Front fender-RH <i>new</i>                     |          | \$744.20 | x   |
| 26  | 1   | Front fender cowling-RH <i>torn</i>            |          | \$125.30 | ✓   |
| 27  | 10  | Front fender cowling clips <i>new</i>          | \$6.50   | \$65.00  | 30  |
| 28  | 1   | Front R/H rim <i>new</i>                       |          | \$450.00 | x   |
| 29  | 1   | Rear Boot Lid <i>Distorted</i>                 |          | 1297     | ✓   |
| 30  | 2   | Rear Boot Lid Hinges <i>new</i>                | \$185.20 | \$370.40 | ✓   |
| 31  | 1   | Rear Boot Lid Number Plate <i>new</i>          |          | \$50.00  | ✓   |
| 32  | 2   | Rear Boot Lid Number Plate lamp <i>new</i>     | \$85.20  | \$170.40 | x   |
| 33  | 1   | Rear Boot Lid Inner Lock <i>new</i>            |          | \$215.20 | ✓   |
| 34  | 2   | Rear Boot Lid side lamp <i>new</i>             | 608      | 1216     | ✓   |
| 35  | 1   | Rear boot lid emble logo <i>new</i>            |          | \$55.00  | ✓   |
| 36  | 1   | boot lid cerato logo <i>new</i>                |          | \$35.00  | ✓   |
| 37  | 1   | boot lid RH logo <i>new</i>                    |          | \$35.00  | ✓   |
| 38  | 1   | BOOT lid inner rubber <i>new</i>               |          | \$188.00 | ✓   |
| 39  | 1   | BOOT lid Centre lamp <i>new</i>                |          | \$690    | ✓   |
| 40  | 2   | rear Boot Lid side reflector chrome <i>new</i> | \$110.20 | \$220.40 | x   |
| 41  | 1   | boot lid insulation <i>new</i>                 |          | \$255.20 | ✓   |
| 42  | 2   | rear Boot Lid signal lamp <i>new</i>           | \$75.20  | \$150.40 | x   |
| 43  | 2   | Rear tail lamp <i>new</i>                      | \$385.20 | \$770.40 | ✓   |
| 44  | 4   | Rear tail lamp clips <i>new</i>                | \$6.50   | \$26.00  | ✓   |
| 45  | 2   | Rear tail lamp panel <i>new</i>                | \$212.00 | \$424.00 | 212 |
| 46  | 1   | rear fender RH <i>new</i>                      |          | 1812     | ✓   |
| 47  | 2   | Rear fender inner trim <i>new</i>              | \$421.20 | \$842.40 | 245 |

|    |    |                                                    |          |            |      |
|----|----|----------------------------------------------------|----------|------------|------|
| 48 | 10 | Rear fender inner trim clips <i>new</i>            | \$6.50   | \$65.00    | 30.  |
| 49 | 1  | Rear Bumper <i>Distorted</i>                       |          | \$785.20   | 660  |
| 50 | 4  | Rear Bumper reverse sensor <i>new</i>              | \$223.00 | \$892.00   | 280. |
| 51 | 5  | Rear Bumper Side Bracket <i>new</i>                | \$75.20  | \$376.00   | 80.  |
| 52 | 1  | Rear Bumper lower cover <i>Delid</i>               |          | \$385.20   | 85.  |
| 53 | 1  | Rear Bumper reinforcement <i>new</i>               |          | \$425.10   | 385. |
| 54 | 2  | Rear Bumper mud shield                             | \$66.20  | \$132.40   | X    |
| 55 | 4  | Rear Bumper mud shield clips <i>new</i>            | \$6.50   | \$26.00    | X    |
| 56 | 1  | Rear Bumper inner sponge                           |          | \$137.80   | e.   |
| 57 | 1  | Rear End Panel <i>Distorted</i>                    |          | \$492.90   | -    |
| 58 | 1  | Rear End Panel Top Garnish <i>Delid</i>            |          | \$185.20   | -    |
| 59 | 1  | Rear spare tire panel <i>Distorted</i>             |          | \$1,223.00 | -    |
| 60 | 1  | Rear spare tire panel top cover <i>crumpled</i>    |          | \$325.10   | 259. |
| 61 | 1  | Rear spare tire panel sealant <i>new</i>           |          | \$250.00   | -    |
| 62 | 1  | Rear Exhaust <i>Bent</i>                           |          | \$952.10   | 758. |
| 63 | 1  | Rear Exhaust chrome aluminum cover <i>crumpled</i> |          | \$160.00   | -    |

17533.20 Subtotal :- \$21,938.70

#### Labour charges

|                                                        |            |       |
|--------------------------------------------------------|------------|-------|
| To Remove & refix <i>front</i> windscreen <i>front</i> | \$120.00   | X     |
| Gum                                                    | \$50.00    | X     |
| To Remove & refix reverse Sensor                       | \$120.00   | 50    |
| to remove & refix rear Windscreen                      | \$120.00   | ✓     |
| Gum                                                    | \$50.00    | ✓     |
| To Remove & refix cushion                              | \$120.00   | 80    |
| To check wheel alignment computer                      | \$150.00   | X     |
| Tuff kote                                              | \$120.00   | ✓     |
| To Check Wiring System                                 | \$80.00    | 60    |
| Towing charges                                         | \$100.00   | 60    |
| to remove & refix rear exhaust                         | \$180.00   | 80    |
| Panel beating                                          | 2400       | 2000  |
| Spray painting                                         | \$1,800.00 | 1600. |

Subtotal :- \$4,710.00

Total:- \$26,648.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 19999.88

c/s: 16K.

20 Days.

16K.

20 Days.