



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303438

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 31/05/2023
Reference CC6/CTI22011593/Rya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMD 8056L
Insured Veh. GBD 8733X
Claim No. SNM22D208249/C02
Policy No. DMCVSNA00097142201
Accident Date 13/11/2022
Inspection Date 28/11/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22011593/Rya3q2 Date: 31/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 8733X	Veh. Inspected	SMD 8056L
	Policy No.	DMCVSNA00097142201	Coverage (\$)	0.00
	Claim No.	SNM22D208249/C02	Excess (\$)	0.00
	Assign From		Assign Date	28/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA FORTUNER 2.7 (A)	c.c	2694
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MHFGX3GS800420113	Colour	BLACK
	Odometer	63675 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/60 R18	DUNLOP	7 mm
	L/H Front Tyre	255/60 R18	DUNLOP	7 mm
	R/H Rear Tyre	255/60 R18	DUNLOP	7 mm
	L/H Rear Tyre	255/60 R18	DUNLOP	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/11/2022	Inspection Date	28/11/2022
	Survey held at	48 TOH GUAN RD EAST #02-146		
	Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 8056L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	610.30	610.30
1	REAR BUMPER LOWER GARNISH	CRACKED	256.00	256.00
	LESS 20% DISCOUNT		-173.26	-
	LESS 25% DISCOUNT		-	-216.58
			693.04	649.72
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS @\$5.50 (SN)	NECESSARY	55.00	30.00
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
1	WRAPPING OF REAR BUMPER (SN)	NECESSARY	800.00	800.00
			1,055.00	830.00
	<u>LABOUR</u>			
	CHECK AND RECTIFY ELECTRICAL WIRING.	NOT NECESSARY	50.00	-
	REMOVE, REPLACE, REFIT AFFECTED ACCIDENT PARTS		300.00	250.00
	SPRAY PAINT (REAR BUMPER).		300.00	250.00
	REMOVE AND REFIT REVERSE SENSOR.		80.00	40.00
			730.00	540.00
GRAND TOTAL			2,478.04	2,019.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CC6/CTI22011593/Rya3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 8056L

RE-INSPECTION

