

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 62504489 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2211-635-TG
DATE : 23-Nov-2022
VEHICLE REG. NO. : SMD8056L
VEHICLE MAKE : TOYOTA FORTUNER 2.7 (A)

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de</i> 866	1	\$ 610.30	\$ 610.30
2	Rear Bumper Lower Garnish <i>cu</i> 256	1	\$ 256.00	\$ 256.00
				649.50
				Parts Less 20%
				\$ (173.26)
				Total Spare Parts
				\$ 693.04
SPECIAL NETT				
3	Rear Bumper Clips <i>new</i>	10	\$ 5.50	\$ 55.00 <i>30</i>
4	Rear Reverse Sensor <i>? XAN</i> 830	1	\$ 200.00	\$ 200.00
5	Wrapping of Rear Bumper <i>new</i>	1	\$ 800.00	\$ 800.00 <i>? price</i>
				Total Special Nett
				\$ 1,055.00
LABOUR				
5	Remove, Replace, Refit Affected Accident Parts	1	\$ 300.00	\$ 300.00 <i>250</i>
6	Spray Paint (Rear Bumper) 540	1	\$ 300.00	\$ 300.00 <i>250</i>
7	Remove and Refit Reverse Sensor	1	\$ 80.00	\$ 80.00 <i>40</i>
8	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00 <i>XAN</i>
				Total Labour
				\$ 730.00
				Amount Before Excess
				\$ 2,478.04
				Add GST @ 7%
				173.46
				Total Amount Payable
				\$ 2,651.50

Estimate prepared by: JAMES TAN

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

649.50
830.00
540.00
2019.50
208
1615.60
45- \$1,600 / 3 days
Rasul
Hp 90010068
3 days
4/5
28/11/22 @ 1610
Reg after repair